

Operating Instructions

Viomax CAS51D

Photometric sensor for SAC or nitrate measurement






Table of contents

1	About this document	3	11	Repair	39
1.1	Warnings	3	11.1	General notes	39
1.2	Symbols	3	11.2	Spare parts	39
1.3	Documentation	3	11.3	Return	39
			11.4	Disposal	39
2	Basic safety instructions	4	12	Accessories	40
2.1	Requirements for the personnel	4	12.1	Device-specific accessories	40
2.2	Intended use	4			
2.3	Workplace safety	4	13	Technical data	42
2.4	Operation safety	5	13.1	Input	42
2.5	Product Safety	5	13.2	Performance characteristics	43
			13.3	Environment	44
3	Product description	6	13.4	Process	44
3.1	Product design	6	13.5	Mechanical construction	44
3.2	Mode of operation	6			
4	Incoming acceptance and product identification	10	Index	45	
4.1	Incoming acceptance	10			
4.2	Product identification	10			
4.3	Scope of delivery	11			
4.4	Certificates and approvals	11			
5	Mounting	12			
5.1	Mounting requirements	12			
5.2	Mounting the sensor	16			
5.3	Mounting the cleaning unit	22			
5.4	Post-mounting check	23			
6	Electrical connection	24			
6.1	Connecting to the transmitter	24			
6.2	Ensuring the degree of protection	25			
6.3	Post-connection check	26			
7	Commissioning	27			
7.1	Function check	27			
8	Operation	28			
8.1	Calibration	28			
8.2	Cyclic cleaning	36			
9	Diagnostics and troubleshooting ...	37			
10	Maintenance	38			
10.1	Maintenance intervals	38			
10.2	Cleaning the sensor	38			
10.3	Maintenance of optical filters and strobe lamp	39			









1 About this document

1.1 Warnings



Structure of information	Meaning
 DANGER Causes (/consequences) If necessary, Consequences of non-compliance (if applicable) ► Corrective action	This symbol alerts you to a dangerous situation. Failure to avoid the dangerous situation will result in a fatal or serious injury.
 WARNING Causes (/consequences) If necessary, Consequences of non-compliance (if applicable) ► Corrective action	This symbol alerts you to a dangerous situation. Failure to avoid the dangerous situation can result in a fatal or serious injury.
 CAUTION Causes (/consequences) If necessary, Consequences of non-compliance (if applicable) ► Corrective action	This symbol alerts you to a dangerous situation. Failure to avoid this situation can result in minor or more serious injuries.
NOTICE Cause/situation If necessary, Consequences of non-compliance (if applicable) ► Action/note	This symbol alerts you to situations which may result in damage to property.

1.2 Symbols

1.2.1 Symbols used

-  Additional information, tips
-  Permitted
-  Recommended
-  Not permitted or not recommended
-  Reference to device documentation
-  Reference to page
-  Reference to graphic
-  Result of an individual step

1.2.2 Symbols on the device

-  Reference to device documentation
-  Do not dispose of products bearing this marking as unsorted municipal waste. Instead, return them to the manufacturer for disposal under the applicable conditions.

1.3 Documentation


The following manuals, which complement these Operating Instructions, can be found on the product pages on the Internet:

-  Technical Information Viomax CAS51D, TI00459C

2 Basic safety instructions

2.1 Requirements for the personnel

- Installation, commissioning, operation and maintenance of the measuring system may be carried out only by specially trained technical personnel.
- The technical personnel must be authorized by the plant operator to carry out the specified activities.
- The electrical connection may be performed only by an electrical technician.
- The technical personnel must have read and understood these Operating Instructions and must follow the instructions contained therein.
- Faults at the measuring point may only be rectified by authorized and specially trained personnel.

 Repairs not described in the Operating Instructions provided must be carried out only directly at the manufacturer's site or by the service organization.

2.2 Intended use

Viomax CAS5 1D is a photometric sensor for SAC or nitrate measurement in liquid media.

The sensor is particularly suited for use in the following applications:

- Monitoring and regulating water treatment plants
- Monitoring surface waters

SAC measurement

- Organic load in WWTP inlet
- Organic load WWTP outlet
- Discharger monitoring
- Organic load in drinking water

Nitrate measurement

- Nitrate measurement in natural bodies of water
- Monitoring nitrate content in WWTP outlet
- Monitoring nitrate content in aeration basins
- Monitoring and optimizing denitrification phases

Any use other than that intended puts the safety of people and the measuring system at risk. Therefore, any other use is not permitted.

The manufacturer is not liable for harm caused by improper or unintended use.

2.3 Workplace safety

CAUTION

UV light

UV light can damage the eyes and skin!

- ▶ Never look into the measuring gap while the device is in operation.

As the user, you are responsible for complying with the following safety conditions:

- Installation guidelines
- Local standards and regulations

Electromagnetic compatibility

- The product has been tested for electromagnetic compatibility in accordance with the applicable international standards for industrial applications.
- The electromagnetic compatibility indicated applies only to a product that has been connected in accordance with these Operating Instructions.

2.4 Operation safety

Before commissioning the entire measuring point:

1. Verify that all connections are correct.
2. Ensure that electrical cables and hose connections are undamaged.
3. Do not operate damaged products, and protect them against unintentional operation.
4. Label damaged products as defective.

During operation:

- ▶ If faults cannot be rectified, take products out of service and protect them against unintentional operation.

2.5 Product Safety

The product is designed to meet state-of-the-art safety requirements, has been tested, and left the factory in a condition in which it is safe to operate. The relevant regulations and international standards have been observed.

3 Product description

3.1 Product design

The sensor has a diameter of 40 mm and can be operated directly and completely in the process without the need for further sampling (in situ). One version of the sensor measures the amount of nitrate in the medium while another version measures the SAC value of the medium.

The sensor comprises the following components:


- Power supply
- High-voltage generation for the strobe lamp
- Measurement gap
 - Central component in which the measuring light interacts with the medium.
- Receiver assembly
 - Detect the measuring signals, digitize them and process them to form a measured value.
- Controller
 - Responsible for controlling internal sensor processes and transmitting data.


All data - including the calibration data - are stored in the sensor. The sensor can be precalibrated and used at a measuring point, calibrated externally, or used for several measuring points with different calibrations.

3.2 Mode of operation

3.2.1 Measuring principle

The light from a pulsed, highly stable strobe lamp (item 3) passes through the measurement gap (item 2). A beam splitter (item 6) directs the light beam to the two receivers (items 1 and 5). A filter in front of the receivers only lets through light in the measuring wavelength or reference wavelength.



 1 *Measuring principle of nitrate sensor*

- 1 *Measuring receiver with filter*
- 2 *Measurement gap*
- 3 *Strobe lamp*
- 4 *Optical window*
- 5 *Reference receiver with filter*
- 6 *Beam splitter*

Within the measuring gap, the medium (water, dissolved ingredients, and particles) absorbs light across the entire spectrum. In the measuring wavelength range, the measured component ¹⁾ takes an additional amount of energy from the light.

For the calculation of the measured value, the ratio of the light signal of the measuring wavelength to the light signal of the reference wavelength is calculated in order to minimize the effect of turbidity and lamp aging.

This change in the ratio can be converted to determine the nitrate concentration or the SAC value. This dependency is non-linear.

Conclusion:

- Long measurement paths ²⁾ measurement gap are required for detecting low concentrations of the measured component.
This is achieved in nitrate measurement with the measurement gap 8 mm (0.31 in) and in SAC measurement with the 40 mm (1.57 in) measurement gap for clear water samples.
- For high turbidity values, longer measuring paths result in the total absorption of light - the measured values are no longer valid.
For media with high turbidity (such as in activated sludge applications), the nitrate sensor with the 2 mm (0.08 in) measurement gap is recommended. Alternatively, a nitrate sensor with the 8 mm (0.31 in) measurement gap can be used with an appropriate sample preparation.
The SAC sensor with the 2 mm (0.08 in) measurement gap is ideal for measuring the organic load in the inlet of municipal wastewater treatment plants.

3.2.2 Nitrate measurement

The sensor is designed for measuring nitrate. As nitrite is also measured, it could also be regarded as an NO_x sensor.

Nitrate ions absorb UV light in the range of approx. 190 to 230 nm. Nitrite ions have a similar absorption rate in the same range.

The sensor measures the light intensity of the 214 nm wavelength (measuring channel). At this wavelength, nitrate and nitrite ions absorb light in proportion to their concentration, while the light intensity in the reference channel remains virtually unchanged at 254 nm.

Interference factors, such as turbidity, fouling or organic hydrocarbons, are minimized.

The signal ratio between the reference wavelength and measurement wavelength constitutes the measurement result. This ratio is converted to the concentration of nitrate using the calibration curve programmed into the sensor.

3.2.3 Cross-interference when measuring with the nitrate version

The following have a direct impact on the measuring range:

- Total solids (TS) and turbidity
- Sludge properties
- Nitrite

Trends:

- A higher proportion of TS or greater turbidity reduces the upper end of the measuring range, resulting in a smaller measuring range.
- High COD ³⁾ levels reduce the upper end of the measuring range, resulting in a smaller measuring range.
- Nitrite is measured as nitrate, thus resulting in a higher measured value.

1) Nitrate or substances that contribute to the spectral absorption coefficient (SAC)

2) Measurement path = Open path length through the

3) COD = Chemical Oxygen Demand

The following can be deduced from the interdependencies cited above:

- Sludge floc causes scattering in the medium, resulting in the attenuation of both the measuring and reference signal to varying degrees. This in turn can bring about a change in the nitrate value due to turbidity.
- High concentrations of oxidizable substances ⁴⁾ in the medium may result in an increase in the measured value.
- Nitrite absorbs light in a similar wavelength range to nitrate and is measured along with nitrate. The dependency is constant: 1.0 mg/l nitrite is displayed as 0.8 mg/l nitrate.
- An adjustment to the customer process is worthwhile in this case.

3.2.4 SAC measurement

Many organic substances absorb light in the range of 254 nm. In the SAC sensor, absorption on the measuring wavelength (254 nm) is compared with the largely unaffected reference measurement at 550 nm.

KHP (potassium hydrogen phthalate $C_8H_5KO_4$) is the established organic reference in SAC measurement operations. That is why the sensor is calibrated in the factory using KHP.

The SAC value can be regarded as a trend indicator of the organic load in a medium. For this purpose, it is converted to COD, TOC, BOD and DOC ⁵⁾ using predefined, adjustable factors:

- $c(\text{TOC}) = 0.4705 \times c(\text{KHP})$
- $c(\text{DOC}) = 0.4705 \times c(\text{KHP})$
- $c(\text{COD}) = 1.176 \times c(\text{KHP})$
- $c(\text{BOD}) = 1.176 \times c(\text{KHP})$

The calculated relationships between COD, TOC, BOD, and DOC with SAC are as follows:

- $\text{TOC} = 0.595 (\text{mg/l} \times \text{m}) \times \text{SAC} (1/\text{m})$
- $\text{DOC} = 0.595 (\text{mg/l} \times \text{m}) \times \text{SAC} (1/\text{m})$
- $\text{COD} = 1.487 (\text{mg/l} \times \text{m}) \times \text{SAC} (1/\text{m})$
- $\text{BOD} = 1.487 (\text{mg/l} \times \text{m}) \times \text{SAC} (1/\text{m})$

Many components that absorb light at 254 nm deviate significantly from KHP in terms of their absorption behavior. For this reason, an adjustment based on the customer process is recommended.

The factors (F) stored in Liquiline can be adapted to the customer process (in the **CAL** menu). You can determine the factor F(Liquiline) to be entered as follows:

$$F(\text{Liquiline}) = \text{laboratory value} / \text{SAC}(\text{CAS5 1D}) \times 0.7909$$

3.2.5 Cross-interference when measuring with the SAC version

The following have a direct impact on the measuring range:

- Turbidity
- Color

4) Specified as COD. Corresponds to the quantity of oxygen that would be required to oxidize the substances if oxygen was the oxidizing agent.

5) Chemical Oxygen Demand (COD), Total Organic Carbon (TOC), Biochemical Oxygen Demand (BOD), Dissolved Organic Carbon (DOC)

Trends:


- Oxidizable substances, absorbing at 550 nm, corrupt the measurement result. In instances of this nature, a comparison or calibration is necessary.
- Coloration that absorbs in the green spectral range increases the measured value.
- Oxidizable substances with spectral properties that differ to those of KHP (potassium hydrogen phthalate) provide measurement results that can deviate from the factory calibration. In instances of this nature, a comparison or adjustment is necessary.
- A higher proportion of TS or greater turbidity reduces the upper end of the measuring range, resulting in a smaller measuring range.
- Sludge floc causes scattering in the medium, resulting in the attenuation of both the measuring and reference signal to varying degrees. This in turn can bring about a change in the measured value due to turbidity.

4 Incoming acceptance and product identification

4.1 Incoming acceptance

On receipt of the delivery:

1. Check the packaging for damage.
 - ↳ Report all damage immediately to the manufacturer.
Do not install damaged components.
2. Check the scope of delivery using the delivery note.
3. Compare the data on the nameplate with the order specifications on the delivery note.
4. Check the technical documentation and all other necessary documents, e.g. certificates, to ensure they are complete.

 If one of the conditions is not satisfied, contact the manufacturer.

4.2 Product identification

4.2.1 Nameplate

The nameplate provides you with the following information on your device:

- Manufacturer identification
 - Extended order code
 - Serial number
 - Safety information and warnings
- ▶ Compare the information on the nameplate with the order.

4.2.2 Identifying the product

Product page

www.endress.com/cas51d

Interpreting the order code

The order code and serial number of your product can be found in the following locations:

- On the nameplate
- In the delivery papers

Obtaining information on the product

1. Go to www.endress.com.
2. Page search (magnifying glass symbol): Enter valid serial number.
3. Search (magnifying glass).
 - ↳ The product structure is displayed in a popup window.
4. Click the product overview.
 - ↳ A new window opens. Here you fill information pertaining to your device, including the product documentation.

4.2.3 Manufacturer address

Endress+Hauser Conducta GmbH+Co. KG
Dieselstraße 24
70839 Gerlingen
Germany

4.3 Scope of delivery

The delivery comprises:

- Sensor in the version ordered
- Operating Instructions
- ▶ If you have any queries:
Please contact your supplier or local sales center.

4.4 Certificates and approvals



Current certificates and approvals for the product are available at www.endress.com on the relevant product page:

1. Select the product using the filters and search field.
2. Open the product page.
3. Select **Downloads**.

5 Mounting


5.1 Mounting requirements

5.1.1 Dimensions



2 Dimensions of sensor with measurement gap 2 mm (0.08 in). Unit: mm (in)

3 Dimensions of sensor with measurement gap 8 mm (0.31 in). Unit: mm (in)



4 Dimensions of sensor with measurement gap
40 mm (1.57 in). Unit: mm (in)


5.1.2 Installation instructions

1. Do not install the device in places where air pockets and foam bubbles form.
2. Choose a mounting location that can be easily accessed at a later stage.
3. Ensure that upright posts and assemblies are fully secured and vibration-free.
4. Align the device so that the measurement gap is rinsed by the flow of medium.
5. Do not install the sensor above aeration discs. Oxygen bubbles may accumulate on the optical windows of the sensor, leading to inaccurate measurements.
6. Select an installation location that produces a typical nitrate concentration/a typical SAC value for the application in question.

To ensure correct measurement, the optical windows on the sensor must be free from any sedimentation. The best way to ensure this is through the use of a cleaning unit (accessory) operated by compressed air.

- For horizontal orientations:
Mount the sensor in such a way that air bubbles can escape from the measurement gap (do not point it downwards).


5.1.3 Orientation




- ▶ Align the sensor in such a way that the measurement gap is rinsed with the flow of medium and air bubbles are removed.

5 Sensor orientation, arrow = direction of flow

Flexdip CYA112 wastewater assembly and Flexdip CYH112 holder



6 Horizontal, fixed installation



7 Suspended vertically from a chain


The installation angle is 90°.

- ▶ Align the sensor in such a way that the measurement gap is rinsed with the flow of medium and air bubbles are removed.

The installation angle is 0°. Tried and tested arrangement for operation in aerated zones.

- ▶ Ensure that the sensor is adequately cleaned. There must be no buildup on the optical windows of the sensor.


Flow assembly CAV01



8 Horizontal, in flow assembly CAV01, arrow indicates the flow direction

- 1 Sensor Viomax CAS51D
- 2 Flow assembly
- 3 Medium inlet
- 4 Medium outlet

Flowfit CYA251 flow assembly



A0032901


9 *Horizontally, in flow assembly CYA251, arrow points in the direction of flow*

- 1 *Sensor Viomax CAS51D*
- 2 *Rinse connection*
- 3 *Medium outlet*
- 4 *Flow assembly*
- 5 *Cap*
- 6 *Medium inlet*

5.2 Mounting the sensor

5.2.1 Immersion operation


Fixed installation with wastewater assembly



A0013347

10 Installation on railing

- 1 Flexdip CYA112 wastewater assembly
- 2 Holder Flexdip CYH112
- 3 Rail
- 4 Viomax CAS51D




A0013215

11 Installation with upright post

- 1 Weather protection cover
- 2 Liquiline CM44x multi-channel transmitter
- 3 Flexdip CYA112 wastewater assembly
- 4 Viomax CAS51D
- 5 Holder Flexdip CYH112

This type of installation is particularly suitable for strong or turbulent flow (>0.5 m/s (1.6 ft/s)) in basins or channels. A cleaning unit (accessory) operated by compressed air significantly extends the maintenance intervals for the sensor.


Installation with chain retainer



A0013348

12 Chain retainer on railing

- 1 Wastewater assembly Flexdip CYA112
- 2 Flexdip CYH112 holder
- 3 Rail
- 4 Viomax CAS51D



A0013351

13 Chain retainer on upright post


- 1 Protective cover
- 2 Liquiline CM44x multi-channel transmitter
- 3 Wastewater assembly Flexdip CYA112
- 4 Viomax CAS51D
- 5 Flexdip CYH112 holder

The chain retainer is particularly suitable for applications that require a sufficient distance between the mounting location and the edge of the aeration basin. As the assembly is freely suspended, any vibration of the upright post is practically ruled out.

The swinging movement of the chain retainer enhances the self-cleaning effect of the optics. A cleaning unit (accessory) operated by compressed air significantly extends the maintenance intervals for the sensor.

5.2.2 Flow operation


Flow assembly CAV01




A0055544

14 Measuring system with flow assembly CAV01

- 1 Transmitter
- 2 Sensor Viomax CAS5 1D
- 3 Holder
- 4 Flow assembly

 Mount the sensor in the assembly in accordance with the Operating Instructions (BA02211C).

Mounting the assembly in the bypass



A0055543

15 Connection diagram with bypass


- 1 Main pipe
- 2 Medium sampling
- 3 Adjustment and shut-off valve or orifice plate
- 4 Medium outlet
- 5 Medium return
- 6 Adjustment and shut-off valve
- 7 Flow assembly
- 8 Medium inlet
- p1 Pressure
- p2 Pressure

To achieve flow through the assembly with a bypass, pressure p1 must be higher than pressure p2. No measures to increase pressure are required for branch pipes that branch off from the main pipe (no return medium).

1. Connect the medium inlet and outlet to the hose connections of the assembly.
↳ The assembly is filled from below and is therefore self-venting.
2. Install an orifice plate or adjustment valve in the main pipe to ensure that pressure p_1 is higher than pressure p_2 .
3. Make sure that the flow is at least 100 ml/h (0.026 gal/h).
4. Take the extended response times into consideration.

Mounting the assembly in open outlet

As an alternative to operation in the bypass, it is also possible to direct the sample flow from a filter unit with an open outlet through the assembly:




16 Connection diagram with open outlet, arrow points in the flow direction

- 1 Pump
- 2 Flow assembly
- 3 Open outlet
- 4 Filter unit

A0055542

Flowfit CYA251 flow assembly




A0032917

17 Measuring system with CYA251

- 1 Transmitter
- 2 Flow assembly
- 3 Medium outlet
- 4 Cap
- 5 Medium inlet
- 6 Sensor Viomax CAS5 1D

 Mount the sensor in the assembly in accordance with the Operating Instructions (BA00495C).

Mounting the assembly in the bypass



A0056262

18 Connection diagram

- | | |
|--|-------------------|
| 1 Main pipe | 6 Flow assembly |
| 2 Adjustment and shut-off valve or orifice plate | 7 Medium inlet |
| 3 Medium outlet | 8 Medium sampling |
| 4 Medium return | p1 Pressure |
| 5 Adjustment and shut-off valve | p1 Pressure |


To achieve flow through the assembly with a bypass, pressure p1 must be higher than pressure p2. No measures to increase pressure are required for branch pipes that branch off from the main pipe (no return medium).

1. Connect the medium inlet and outlet to the hose connections of the assembly.
 - ↳ The assembly is filled from below and is therefore self-venting.
2. Install an orifice plate or adjustment valve in the main pipe to ensure that pressure p1 is higher than pressure p2.

3. Make sure that the flow is at least 100 l/h (26.5 gal/h).
4. Take the extended response times into consideration.

Mounting the assembly in open outlet

As an alternative to operation in the bypass, it is also possible to direct the sample flow from a filter unit with an open outlet through the assembly.




A0032921

19 Flow assembly with open outlet, arrow points in the flow direction

- 1 Pump
- 2 Flow assembly
- 3 Open outlet
- 4 Filter unit

5.3 Mounting the cleaning unit



20 Compressed air cleaning

A Cleaning for 2 mm (0.08 in) and 8 mm (0.31 in) measurement gap


B Cleaning for 40 mm (1.57 in) measurement gap

1 Adapter 8 mm (0.31)

2 300 mm (11.81 in) Hose (Ø = 6 mm (0.24 in))

3 Gland 6 mm (0.24 in) or 6.35 mm (0.25 in) for 2 mm (0.08 in) and 8 mm (0.31 in) measurement gap

4 Gland 6 mm (0.24 in) or 6.35 mm (0.25 in) for measurement gap 40 mm (1.57 in)

 The air cleaning system is not suitable for use in drinking water according to NSF/ANSI Standard 61.

CAUTION

Residual medium and high temperatures


Risk of injury!

- ▶ When working with parts that are in contact with the medium, protect against residual medium and elevated temperatures.
- ▶ Wear protective goggles and safety gloves.

Preparatory steps:


1. Mount the air cleaning system before installing the sensor in the measuring point.
2. Remove the sensor from the medium if the device is already in the process.
3. Clean the sensor.

Sensor with 2 mm (0.08 in) or 8 mm (0.31 in) measurement gap :



Insert the elbow plug into the mounting borehole behind the measurement gap as far as the end stop (hand-tight).


2. Screw the elbow plug tight.




Connect the hose of the compressed air supply at the installation location to the opening of the elbow plug.

4. Use the hose piece with hose coupling provided with the sensor if desired.

Sensor with measurement gap 40 mm (1.57 in):



Insert the air distributor into the mounting boreholes behind the measurement gap as far as the end stop (hand-tight).



Connect the hose of the compressed air supply to the opening of the elbow plug.

3. Use the hose piece with hose coupling provided with the sensor if desired.

5.4 Post-mounting check

Put the sensor into operation only if you can answer "yes" to the following questions:

- Are the sensor and cable undamaged?
- Is the orientation correct?
- Is the sensor installed in an assembly and not freely suspended from the cable?
- Is the cable routed so that it is completely dry (routed inside an assembly if necessary)?

6 Electrical connection

⚠ WARNING

Device is live!

Incorrect connection may result in injury or death!

- ▶ The electrical connection may be performed only by an electrical technician.
- ▶ The electrical technician must have read and understood these Operating Instructions and must follow the instructions contained therein.
- ▶ **Prior** to commencing connection work, ensure that no voltage is present on any cable.

6.1 Connecting to the transmitter

6.1.1 Connecting the cable shield to the grounding rail of the transmitter

⚠ WARNING

Sensor not grounded

If maintenance work (lamp replacement) is not performed correctly, moisture or dirt may penetrate the housing and cause an electric shock to anyone who touches it.


- ▶ To guarantee safety in the workplace, always connect the sensor's cable shield to the grounding rail of the transmitter or control cabinet.

Device cable must be shielded cables.

i Only use terminated original cables where possible.


Clamping range of cable clamps: 4 to 11 mm (0.16 to 0.43 in)

Cable sample (does not necessarily correspond to the original cable supplied)




21 Terminated cable

- 1 Outer shield (exposed)
- 2 Cable cores with ferrules
- 3 Cable sheath (insulation)



22 Connect the cable to the grounding clamp

4 Grounding clamp



23 Press the cable into the grounding clamp

The cable shield is grounded using the grounding clamp ¹⁾

1) Please note the instructions in the "Ensuring the degree of protection" section


1. Loosen a suitable cable gland on the bottom of the housing.
2. Remove the dummy plug.
3. Attach the gland to the cable end, making sure the gland is facing the right direction.
4. Pull the cable through the gland and into the housing.
5. Route the cable in the housing in such a way that the **exposed** cable shield fits into one of the cable clamps and the cable cores can be easily routed as far as the connection plug on the electronics module.

6. Connect the cable to the cable clamp.
7. Clamp the cable.
8. Connect cable cores as per the wiring diagram.
9. Tighten the cable gland from outside.

6.1.2 Connecting the sensor

The following connection options are available:

- via M12 connector (version: fixed cable, M12 connector)
- via sensor cable to the plug-in terminals of a sensor input on the transmitter (version: fixed cable, end sleeves)



24 Sensor connection to sensor input (left) or via M12 connector (right)

The maximum cable length is 100 m (328.1 ft).

6.2 Ensuring the degree of protection

Only the mechanical and electrical connections which are described in these instructions, and which are necessary for the required intended use, may be established on the device delivered.

- Exercise care when carrying out the work.


Otherwise, the individual types of protection (Ingress Protection (IP), electrical safety, EMC interference immunity) agreed for this product can no longer be guaranteed due, for example, to covers being left off or cable (ends) that are loose or insufficiently secured.

6.3 Post-connection check

Device health and specifications	Action
Is the outside of the sensor, assembly or cable free from damage?	▶ Perform a visual inspection.
Electrical connection	Action
Are the mounted cables strain-relieved and not twisted?	▶ Perform a visual inspection. ▶ Untwist the cables.
Is a sufficient length of the cable cores stripped, and are the cores positioned in the terminal correctly?	▶ Perform a visual inspection. ▶ Pull gently to check they are seated correctly.
Are the power supply and signal lines correctly connected?	▶ Refer to the wiring diagram for the transmitter.
Are all screw terminals tightened?	▶ Tighten the screw terminals.
Are all the cable entries installed, tightened and leak-tight?	▶ Perform a visual inspection. In the case of lateral cable entries:
Are all cable entries mounted on the side or pointing downwards?	▶ Point cable loops downward so that water can drip off.

7 Commissioning

7.1 Function check

-  Before commissioning, ensure that:
- The sensor is correctly installed
 - The electrical connection is correct
- ▶ Before commissioning, check the chemical material compatibility, the temperature range and the pressure range.

8 Operation

- ▶ Verify that a representative measured value is displayed on the transmitter.
- ▶ For solids that have a tendency to form deposits, ensure that the medium is mixed sufficiently.

8.1 Calibration

Calibration is performed in the process by comparing the values to an external standard method, by calibrating with standard solutions or by using a combination of both (addition of standard).

8.1.1 Factory calibration

Nitrate sensor

The sensor is precalibrated on leaving the factory.

As such, it can be used in a wide range of clear water measurements without the need for additional calibration.

SAC sensor

The sensor is precalibrated on leaving the factory (calibrated with KHP).

Calibration to the customer process is nevertheless advantageous in the majority of cases. Reason: Organic compounds other than KHP react differently in the spectrum.

The factory calibration is based on 20 calibration points and is adjusted at three points during production. The factory calibration cannot be deleted and can be retrieved at any time. Single-point and two-point calibrations - performed as customer calibrations - are referenced to this factory calibration.

8.1.2 Types of calibration

In addition to the factory calibrations, which cannot be changed, the sensor contains six additional data records for storing process calibrations or for adjustment to the relevant measuring point (application). Each calibration data record can have up to five calibration points.

The sensor offers a wide range of options for adapting the measurement to the application in question:

- Calibration or adjustment (1 to 5 points)
- Entry of a factor (multiplication of the measured values by a constant factor)
- Entry of an offset (addition/subtraction of a constant factor to/from the measured values)
- Duplication of factory calibration data records

One-point or multipoint calibration

Do not remove the sensor from the medium for calibration purposes; it can be calibrated directly in the application.

1. WARNING

Mineral acids

Risk of serious or fatal injury from caustic burns!

- ▶ Wear goggles to protect eyes.
- ▶ Wear protective gloves and appropriate protective clothing.
- ▶ Avoid all contact with the eyes, mouth and skin.

For the calibration, ensure that the measuring gap is not soiled with deposit buildup: Clean the measurement gap with optical windows before the calibration (with 5 to 10% H₃PO₄ or 5 to 10% HCl or 5 to 10% H₂SO₄. Remove dirt and deposits).

2. To perform the calibration, immerse the sensor in the medium in such a way that the measuring gap is completely filled with the medium.
 - ↳ All air bubbles and air pockets must be cleaned out of the measuring gap during immersion.


Lines interpolate between the calibration points.

- ▶ Give your calibration data records meaningful and useful names.

For example, the name can contain the name of the application on which the data record was originally based. This makes it easier to distinguish between different data records.

Principle of a one-point calibration

The measured error between the measured value of the device and the laboratory measured value is too large. This is corrected by a 1-point calibration.




25 Principle of a 1-point calibration

- x Measured value
- y Target sample value
- a Factory calibration
- b Application calibration

1. Select data record.
2. Set the calibration point in the medium and enter the target sample value (laboratory value).

Principle of a two-point calibration

Measured value deviations are to be compensated at 2 different points in an application (e.g. maximum and minimum value of the application). This aims to ensure a maximum level of measurement accuracy between these two extreme values.



A0039325


26 Principle of a two-point calibration

x Measured value
 y Target sample value
 a Factory calibration
 b Application calibration

1. Select a data set.
2. Set 2 different calibration points in the medium and enter the corresponding set points.

i A linear extrapolation is performed outside the calibrated operational range.
 The calibration curve must be monotonically increasing.

Principle of multiple point calibration



A0039322

27 Principle of multipoint calibration (3 points)

x Measured value
 y Target sample value
 a Factory calibration
 b Application calibration

1. Select the data set.
 2. Set 3 different calibration points in the medium and specify the corresponding set value.
- i** A linear extrapolation is performed outside the calibrated operational range.
 The calibration curve must be monotonically increasing.


Principle of entering a factor

With the "Factor" function, the measured values are multiplied by a constant factor. The functionality corresponds to that of a 1-point calibration.

Example:

This type of adjustment can be selected if the measured values are compared to the laboratory values over a longer period of time and all values are too low by a constant factor, e.g. 10%, in relation to the laboratory value (target sample value).

In the example, the adjustment is made by entering the factor 1.1.




A0039329

28 Principle of factor calibration

- x* Measured value
- y* Target sample value
- a* Factory calibration
- b* Factor calibration

Principle of entering an offset

With the "Offset" function, the measured values are offset by a constant amount (added or subtracted).



29 Principle of an offset

- x Measured value
- y Target sample value
- a Factory calibration
- b Offset calibration

8.1.3 Stability criterion

During the calibration process, the measured values are checked to ensure that they remain constant.

You use the stability criterion to define maximum deviations during a calibration. Only a measured value within the specified deviation is accepted.

The stability criterion includes:

- The maximum permitted deviation in temperature measurement
- The maximum permitted deviation in measured value as a %
- the minimum time frame in which these values must be maintained

If the measured value or temperature deviate more than is permitted in the specified time frame, this calibration point becomes invalid and a warning is issued.

The stability criteria are used to monitor the quality of the individual calibration points in the course of the calibration process. The aim is to achieve the best possible calibration quality in the shortest possible time frame while taking external conditions into account.

- For high-precision calibrations in the laboratory, the maximum deviation permitted in the measured value can be kept as small as possible and the time frame selected can be as long as possible..
- For calibrations in the field in adverse weather and environmental conditions, the maximum deviation permitted in the measured value can be kept suitably large and the time frame selected can be kept suitably short.



Operating Instructions Memosens inputs BA01245C

8.1.4 Determining the reference values in the laboratory

Nitrate sensor

1. Take a representative sample of the medium.

2. Take suitable measures to ensure that the process of nitrate reduction in the sample does not progress any further, such as immediate filtration (0.45 µm) of the sample as per DIN 38402.
3. Determine the concentration of nitrate in the sample using the laboratory method (for example, by colorimetric means using a cuvette test - the standard method as per DIN 38405 Part 9).

SAC sensor

1. Take a representative sample of the medium.
2. Take suitable measures to ensure that the process of biological and chemical reduction in the sample does not progress any further.
3. Determine the measured values of your sample array using the laboratory method (for example, by colorimetric means using a cuvette test).

8.1.5 Nitrate sensor

Processes with nitrate values > 0.1 mg/l

1. Take sample and determine nitrate concentration in the laboratory.
2. Calibrate and adjust the sensor using the laboratory value.

Processes with very different nitrate values

1. At time A, take a sample with a high concentration, and measure and calibrate the sample.
2. At time B - which can be a few days later - take a sample with a low concentration, and measure and calibrate the second value.

Calibration with the addition of standard

If the sludge parameters tend to be constant, you can perform the calibration with a sample with a low concentration of nitrate and then add standard to the sample.

1. Take a larger sample (bucket) and analyze some of it by colorimetric means.
2. Calibrate the value of the calorimetric measurement in the sensor.
3. Add standard to the sample and determine the laboratory value.
4. Calibrate the laboratory value of the sample with added standard in the sensor.


Avoid incorrect measurements:

- Drinking water may contain higher concentrations of nitrate and is not suitable for zero adjustment. Use fully deionized water to perform zero adjustment.
- During calibration, make sure the sample is homogeneous.
- When calibrating, start with a low concentration and increase the concentrations gradually to prevent nitrate carryover.
- Clean and dry the sensor after a calibration. Ensure that there is no medium residue in the measurement gap. In this way, you avoid mixing the different samples and changing the nitrate concentrations.

8.1.6 SAC sensor

The required data set is activated by selecting the application in question and can be adapted to that application using the following options:

- Calibration (1 to 10 points)
- Entry of a factor (multiplication of the measured values by a constant factor)
- Entry of an offset (addition/subtraction of a constant factor to/from the measured values)
- Duplication of factory calibration data records
- Adjustment of the conversion factors

 Further data sets can be created in the sensor and adapted to the application by means of calibration or by entering a factor or offset.

General calibration steps

1. Take a sample.
2. Determine the SAC value of the sample in the laboratory.
3. Calibrate and adjust the sensor using the laboratory value.

In the SAC sensor version, the calculated variables COD, TOC, BOD and DOC can also be output if desired, in addition to the actual measured variable. These variables are based on the following ratios:


- 1 mg/l KHP = ~1.176 mg/l COD
- 1 mg/l KHP = ~0.4705 mg/l TOC
- 1 mg/l KHP = ~1.176 mg/l BOD
- 1 mg/l KHP = ~0.4705 mg/l DOC

Using other conversion factors

Sometimes the conversion factors for COD, TOC, BOD or DOC are predetermined by control bodies. In such instances, these factors can be adjusted as follows:

1. Copy the factory data set to a free data set of your choice in the SAC basic setting.

A copy is necessary because the factory data set cannot be modified. If you already have another data set, you can change its factors directly.

2. Activate the new data set (in the **Setup** menu).
3. Set the desired factor. (In the **CAL** menu) For factors with corresponding conversions, see →  8.
4. Set the device to the desired measured variable (in the **Setup** menu).

 Operating Instructions Memosens inputs BA01245C.

The SAC sensor can be calibrated for the measured variables SAC, COD, TOC, BOD and DOC.

If the sensor has been calibrated for the measured variable SAC, the conversion factors for COD, TOC, BOD or DOC can be adjusted at a later stage. If calibrated for TOC, COD, BOD or DOC, only the factor for the measured variable in use can be changed subsequently.

Avoid incorrect measurements:

- Drinking water contains many organic elements. The use of fully deionized water is also recommended here for zero adjustment.
- During calibration, make sure the medium is homogeneous.
- Avoid any carryover of organic elements during calibration.

Processes with widely varying SAC values

Record the calibration points in different operational states. Example of a WWTP inlet:

- After a rainy period
- In "normal conditions"
- After a dry period

1. Save the points in any data set.
2. Add the lab results pertaining to the points.
3. Activate the calibration once a sufficient number of points have been set.

While this type of calibration can be more time-consuming, it allows the precise adjustment of the measurement technology to the operating conditions of the plant.

8.1.7 Calibrating and adjusting the sensor

To calibrate the sensor, use the same medium sample or sample array that was used to determine the laboratory measured values. The sample array can also be pure standard solutions.

The general sequence of a calibration is as follows:

1. Select data record.
2. Place sensor in medium.
3. During calibration, ensure that the medium is well homogenized.
4. Start the calibration for the measuring point.
5. If only one point should be calibrated:
End the calibration by accepting the calibration data.
↳ Otherwise continue with the next step.
6. Add parent solution to the sample for the 2nd measuring point.
7. Determine the measured value.
8. Calculate the reference value from the laboratory measured value plus the added concentration.
9. Repeat the previous step as often as needed until you have reached the desired number of calibration points (maximum 5).

To avoid incorrect calibration from carryover:

- Always go from a low concentration to a high concentration.
- Clean and dry the sensor after each measurement.
- Make sure to remove medium residue in the sensor gap and in the connection opening for the compressed air (e.g. by rinsing with the next calibration solution).

8.2 Cyclic cleaning

Compressed air is most suitable for automatic cyclic cleaning. There is a connection for compressed air on every sensor. The cleaning unit, which is supplied with the device or can be retrofitted, operates effectively at a rate of 20 l/min (5.4 US gal/min).

The optical windows are optimally cleaned at a pressure of 1.5 to 2 bar (21.8 to 29 psi). Higher pressure may damage the surface of the optical windows.

Type of contamination	Cleaning interval	Cleaning duration
Severe fouling with rapid buildup	5 min	10 s
Low degree of fouling	10 min	10 s


9 Diagnostics and troubleshooting

When troubleshooting, the entire measuring point must be taken into account:

- Transmitter
- Electrical connections and cables
- Assembly
- Sensor

The possible causes of faults in the following table refer primarily to the sensor.

Problem	Check	Remedial action
Blank display, no sensor reaction	<ul style="list-style-type: none"> ■ Mains voltage at transmitter? ■ Sensor connected correctly? ■ Medium flow present? ■ Buildup on optical windows? 	<ol style="list-style-type: none"> 1. Apply mains voltage. 2. Connect sensor correctly. 3. Ensure medium is flowing. 4. Clean sensor.
Display value too high or too low	<ul style="list-style-type: none"> ■ Buildup on optical windows? ■ Gas bubbles present? ■ Sensor calibrated? 	<ol style="list-style-type: none"> 1. Clean. 2. Eliminate gas bubbles. 3. Perform calibration. 4. Check data set and modify if necessary. 5. Inspection at the factory
Display value fluctuating strongly	Gas bubbles present?	<ol style="list-style-type: none"> 1. Eliminate gas bubbles. 2. Check mounting location and select a different mounting location if necessary.

 Pay attention to the troubleshooting information in the Operating Instructions for the transmitter. Check the transmitter if necessary.

10 Maintenance

CAUTION

Acid or medium

Risk of injury, damage to clothing and the system!

- ▶ Wear protective goggles and safety gloves.
- ▶ Clean away splashes on clothes and other objects.

- ▶ You must perform maintenance tasks at regular intervals.

We recommend setting the maintenance times in advance in an operations journal or log.

The maintenance cycle primarily depends on the following:

- The system
- The installation conditions
- The medium in which measurement takes place

10.1 Maintenance intervals

The sensor requires very little maintenance, particularly if a cleaning unit is connected. Nevertheless, maintenance must be performed at regular intervals. Schedule maintenance times in advance in an operations journal or log.

Monthly:	Visual check, clean sensor if necessary. Cleaning intervals depend on the medium.
Every 125 million flashes (= two years at 2 Hz) or at least every four years:	Replace optical filters (manufacturer service team)
Every 250 million flashes (= four years at 2 Hz) or at least every eight years:	Replace strobe lamp (manufacturer service team)

10.2 Cleaning the sensor

Sensor fouling can affect the measurement results and even cause a malfunction.

- ▶ To ensure reliable measurements, clean the sensor at regular intervals. The frequency and intensity of the cleaning depend on the medium.

Clean the sensor:


- As specified in the maintenance schedule
- Before every calibration
- Before returning it for repair

Type of contamination	Cleaning measure
Lime deposits	▶ Immerse the sensor in 1 to 5% hydrochloric acid (for several minutes).
Dirt particles on the optics	▶ Clean the optics with a cleaning cloth.
Deposit buildup on the optics	There may be deposit buildup in the non-visible range (UV). Therefore, always clean the optics. ▶ Wet a cotton bud with 5-10% phosphoric acid or 5-10% hydrochloric acid and use it to clean the optics. ▶ Clean the measurement gap with the cleaning brush that is optionally available.

After cleaning:

- ▶ Rinse the sensor thoroughly with water.

10.3 Maintenance of optical filters and strobe lamp

This work must be performed only by the manufacturer service team. Contact your Sales Center. →  39

 Replacing the optical filter and strobe lamp also entails new factory calibration and adjustment of the sensor.

11 Repair

11.1 General notes

- ▶ Only use spare parts from Endress+Hauser to guarantee the safe and stable functioning of the device.

Detailed information on the spare parts is available at:
www.endress.com/device-viewer

11.2 Spare parts

For more detailed information on spare parts kits, please refer to the "Spare Part Finding Tool" on the Internet:

www.products.endress.com/spareparts_consumables

11.3 Return

The product must be returned if repairs or a factory calibration are required, or if the wrong product was ordered or delivered. As an ISO-certified company and also due to legal regulations, Endress+Hauser is obliged to follow certain procedures when handling any returned products that have been in contact with medium.

To ensure the swift, safe and professional return of the device:

- ▶ Check the website www.endress.com/support/return-material for information on the procedure and general conditions.

11.4 Disposal

The device contains electronic components. The product must be disposed of as electronic waste.

- ▶ Observe the local regulations.

12 Accessories

The following are the most important accessories available at the time this documentation was issued.

Listed accessories are technically compatible with the product in the instructions.

1. Application-specific restrictions of the product combination are possible. Ensure conformity of the measuring point to the application. This is the responsibility of the operator of the measuring point.
2. Pay attention to the information in the instructions for all products, particularly the technical data.
3. For accessories not listed here, please contact your Service or Sales Center.

12.1 Device-specific accessories

12.1.1 Assemblies

Flexdip CYA112

- Immersion assembly for water and wastewater
- Modular assembly system for sensors in open basins, channels and tanks
- Material: PVC or stainless steel
- Product Configurator on the product page: www.endress.com/cya112



Technical Information TI00432C

Flowfit CYA251

- Connection: See product structure
- Material: PVC-U
- Product Configurator on the product page: www.endress.com/cya251



Technical Information TI00495C

CAV01

- Flow assembly
- Material: POM-C
- Product Configurator on the product page: www.endress.com/cav01



Technical Information TI01797C

12.1.2 Holder

Flexdip CYH112

- Modular holder system for sensors and assemblies in open basins, channels and tanks
- For Flexdip CYA112 water and wastewater assemblies
- Can be affixed anywhere: on the ground, on the coping stone, on the wall or directly onto railings.
- Stainless steel version
- Product Configurator on the product page: www.endress.com/cyh112



Technical Information TI00430C

12.1.3 Cleaning

Cleaning brushes

- Cleaning brushes to clean the measurement gap (for all gap sizes)
- Order number: 71485097

Compressed air cleaning for CAS51D

- Pressure: 1.5 to 2 bar (21.8 to 29 psi)
- Measurement gap 2 mm (0.08 in) or 8 mm (0.31 in):
 - 6 mm (0.24 in) (with 300 mm (11.81 in) hose and 8 mm (0.31 in) adapter)
Order number: 71485094
 - 6.35 mm (0.25 in)
Order number: 71485096
- Measurement gap 40 mm (1.57 in):
6 mm (0.24 in) (with 300 mm (11.81 in) hose and 8 mm (0.31 in) adapter)
Order No. 71126757

Compressor

- For compressed air cleaning
- 230 V AC, order number: 71072583
- 115 V AC, order number: 71194623

12.1.4 Standard solutions**Nitrate standard solutions, 1 liter**

- 5 mg/l NO₃-N, order number: CAY342-V10C05AAE
- 10 mg/l NO₃-N, order number: CAY342-V10C10AAE
- 15 mg/l NO₃-N, order number: CAY342-V10C15AAE
- 20 mg/l NO₃-N, order number: CAY342-V20C10AAE
- 30 mg/l NO₃-N, order number: CAY342-V20C30AAE
- 40 mg/l NO₃-N, order number: CAY342-V20C40AAE
- 50 mg/l NO₃-N, order number: CAY342-V20C50AAE

KHP standard solution

CAY451-V10C01AAE, 1000 ml parent solution 5 000 mg/l TOC

13 Technical data

13.1 Input

Measured variables

Nitrate

NO₃-N [mg/l], NO₃ [mg/l]

SAC

SAC [1/m], COD [mg/l], TOC [mg/l], BOD [mg/l], DOC [mg/l], transmission [%]

Measuring range

CAS51D-**A2 (2 mm (0.08 in) measurement gap)	0.1 to 50 mg/l NO ₃ -N 0.4 to 200 mg/l NO ₃ Clear water and sludge activation
CAS51D-**A1 (8 mm (0.31 in) measurement gap)	0.01 to 20 mg/l NO ₃ -N 0.04 to 80 mg/l NO ₃ Clear water (with a COD (KHP) content of up to 125 mg/l and up to 50 FNU turbidity based on mineral kaolin)
CAS51D-**C1 (40 mm (1.57 in) measurement gap)	SAC 0 to 50 1/m COD/BOD 0 to 75 mg/l ¹⁾ TOC/DOC 0 to 30 mg/l ¹⁾ Clear water, low measuring range, drinking water
CAS51D-**C2 (8 mm (0.31 in) measurement gap)	SAC 0 to 250 1/m COD/BOD 0 to 375 mg/l ¹⁾ TOC/DOC 0 to 150 mg/l ¹⁾ Clear water, medium measuring range, drinking water, wastewater treatment plant outlet, monitoring of bodies of water
CAS51D-**C3 (2 mm (0.08 in) measurement gap)	SAC 0 to 1000 1/m COD/BOD 0 to 1500 mg/l ¹⁾ TOC/DOC 0 to 600 mg/l ¹⁾ Organic load in the inlet, discharger control, industrial processes

1) equivalent KHP



The possible measuring range depends strongly on the properties of the medium.

Empirical values for typical COD measuring ranges

Inlet of municipal wastewater treatment plant	0 to 4000 mg/l COD
Influent from milk-processing industry	0 to 10 000 mg/l COD
Influent from chemical industry	0 to 10 000 mg/l COD

13.2 Performance characteristics

Reference conditions 20 °C (68 °F), 1013 hPa (15 psi)

Measurement error ⁶⁾	Nitrate	For 0.1 to 50 mg/l NO ₃ -N (measurement gap 2 mm (0.08 in)): 2 % of full scale value above 10 mg/l 0.4 % of full scale value below 10 mg/l For 0.01 to 20 mg/l NO ₃ -N (measurement gap 8 mm (0.31 in)): 2 % of full scale value above 2 mg/l 0.2 % below 2 mg/l
	SAC	2 % of full scale value for standard measurement with potassium hydrogen phthalate (KHP)

Repeatability ⁶⁾

Nitrate
At least ±0.2 mg/l NO₃-N

SAC
0.5 % of end of measuring range (for homogeneous media)

Detection limits

Nitrate

- CAS51D-AAA1
0.003 mg/l NO₃-N
- CAS51D-AAA2
0.013 mg/l NO₃-N

SAC
In relation to the standard potassium hydrogen phthalate (KHP):

- CAS51D-AAC1
0.045 mg/l COD
- CAS51D-AAC2
0.3 mg/l COD
- CAS51D-AAC3
1.5 mg/l COD

Determination limits

Nitrate

- CAS51D-AAA1
0.01 mg/l NO₃-N
- CAS51D-AAA2
0.043 mg/l NO₃-N

SAC
In relation to the standard potassium hydrogen phthalate (KHP):

- CAS51D-AAC1
0.15 mg/l COD
- CAS51D-AAC2
1.0 mg/l COD
- CAS51D-AAC3
5.0 mg/l COD

Long-term drift

Nitrate
Better than 0.1 mg/l NO₃-N over one week

6) The measurement error contains all the uncertainties of the sensor and transmitter (measuring chain). It does not contain all the uncertainties caused by the reference material and adjustments that may have been performed.

SAC

Better than 0.2 % of end of measuring range over one week

13.3 Environment

Ambient temperature range -20 to 60 °C (-4 to 140 °F)

Storage temperature -20 to 70 °C (-4 to 158 °F)


Degree of protection IP 68 (1 m (3.3 ft) water column, 24 hours, 1 mol/l KCl)

13.4 Process

Process temperature range 5 to 50 °C (41 to 122 °F)

Process pressure range 0.5 to 10 bar (7.3 to 145 psi) absolute

Minimum flow No minimum flow required.

 For solids which have a tendency to form deposits, ensure that sufficient mixing is performed.

13.5 Mechanical construction

Dimensions →  12

Weight Approx. 1.6 kg (3.53 lbs) (without cable)

Materials	Sensor	Stainless steel 1.4404 (AISI 316 L)
	Optical windows	Quartz glass
	O-rings	EPDM

Process connections

- G1 and NPT 3/4"
- Clamp 2" (depending on sensor version)/DIN 32676

Index

A

Accessories	40
Ambient temperature range	44
Approvals	11

C

Cable shield	24
Calibration	
Factory calibration	28
Certifications	11
Check	
Connection	26
Mounting	23
Cleaning	36, 38
Cleaning unit	22
Commissioning	27
Cross-interference	
Nitrate	7
SAC	8
Cyclic cleaning	36

D

Degree of protection	44
Detection limits	43
Determination limits	43
Diagnostics	37
Dimensions	12
Disposal	39

E

Electrical connection	24
Ensuring the degree of protection	25

F

Factor	32
Factory calibration	28
Flow operation	18
Function check	27

I

Identifying the product	10
Immersion operation	16
Incoming acceptance	10
Input	42
Installation instructions	13
Intended use	4
Interpreting the order code	10

L

Long-term drift	43
-----------------	----

M

Maintenance	38
Maintenance intervals	38
Manufacturer address	11
Materials	44
Measured variables	42

Measurement error	43
Measuring principle	6
Measuring range	42
Mechanical construction	44
Minimum flow	44
Mode of operation	6
Mounting	12
Multipoint calibration	31

N

Nameplate	10
Nitrate	7

O

Offset	33
One-point calibration	29
Operation	28
Optical filters	39
Orientation	14

P

Performance characteristics	43
Post-connection check	26
Post-mounting check	23
Process connections	44
Process pressure range	44
Process temperature range	44
Product description	6
Product identification	10
Product page	10

R

Reference conditions	43
Repair	39
Repeatability	43
Return	39

S

SAC	8
Safety Instructions	4
Scope of delivery	11
Sensor	16
Cleaning	38
Connecting	25
Design	6
Dimensions	12
Spare parts kit	39
Stability criterion	33
Storage temperature	44
Strobe lamp	39
Symbols	3

T

Technical data	42
Troubleshooting	37
Two-point calibration	30

U

Use 4

W

Warnings 3

Weight 44

Wiring 24



71669890

www.addresses.endress.com
