Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

1.	Τv	ре	of	de	evice

□ Field device / signal processing device

☐ Monitoring-/operation system/hand held terminal etc.

☐ Modem / interface

Manufacturer : Endress+Hauser Flowtec AG

Device : Vortex Flowmeter

Type : Prowirl 200 PROFIBUS PA (0x1564)

: 7F2B-***G***** Order code

2. Firmware

Previous firmware version : 1.01.00 New firmware version : 1.00.01

How can the previous Local display

firmware version be Nameplate for connections

identified? Configuration and service software e.g. FieldCare

Description of the modifications in comparison to the previous firmware version

No device restart after parameter download Additional process variables:

- - Pressure
 - Degree of overheating Specific volume
- Additional AI channels:
 - Pressure
 - Degree of overheating
 - Specific volume
 - Density
 - Reynolds number

3. Compatibility

Is the operating tool compatible with the installed device firmware?

- ☐ Yes

An update of the DD's (device description) is required for all operating tools in use.



Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

	Is a	firmware update generally recommended?						
		Yes:						
	⊠ No, reason:							
	If the additional properties are not required for the operation of the measurement system, then no firmware update is necessary.							
4. Instruction manual								
	Is a new instruction manual necessary due to the modification of the firmware?							
	□ Yes							
		No						
	Which manual corresponds to the new firmware?							
	De	vice	Communication option	s Manual	Identification			
	Pro	owirl 200	PROFIBUS PA	Operating instructions	BA01222D/06/EN/02. 14			
	The new instruction manuals can be referred in Internet: http://www.endress.com - area "DOWNLOAD" - declaration of the device and kind of manual							
5.	Pri	ice						
	Ch	Change in price of device in comparison with the predecessor version?						
		Yes, new list price and update costs (without installation) are enclosed No						