Manufacturer Information

For users regarding firmware and hardware updates (in accordance with the NAMUR 53 recommendation)

1 Type of device

| \square | Field device / signal processing device Monitoring / operating system | | | | | |
|--------------------------|--|---|---|------------------|--|--|
| Manufacturer | | : | Endress+Hauser GmbH+Co.KG, 79689 Maulburg | | | |
| Product | | : | Gammapilot | | | |
| Part number / Order code | | : | FMG50 | | | |
| Comm Interf | nunication / ace | : | Communication | Device Type | | |
| | | | V01.00.04, HART | Dev. Revision 01 | | |

2 Firmware, Hardware I

Type of change:

- ☑ Firmware version
- □ Hardware I revision

| Old version / revision | : | V01.00.02 Dev. Revision 01 |
|------------------------|---|----------------------------|
| New version / revision | : | V01.00.04 Dev. Revision 01 |

How can the old Firmware version / Hardware I revision number be identified:

1. via DTM (FieldCare / DeviceCare)

2. via Smartblue (Bluetooth Device)

3. via DD (FieldCommunicator)

In the operating menu under: System > Information > Firmware Version.

Description of the modification with respect to the old Firmware version / Hardware I revision:

Major Changes:

- Behavior in the absence of terrestrial background radiation improved.
- Commissioning via RIA15 is now possible without a mandatory restart of the device.
- Improved display functionality if unplugged for a long time.
- HART command 227 improvements.



3 Functional Safety

Impact on Functional Safety:

⊠ No

□ Yes

Changes in safety figures:

🖂 No

 \Box Yes \rightarrow new figures refer to Safety Manual (chapter 5)

4 Compatibility (Firmware, Hardware I)

Is the new Firmware version compatible with the previous version, the installed device drivers, the operating tool compatible / is the new Hardware I revision compatible with the previous revision?

🖂 Yes

□ No, description:

Is a Firmware / Hardware update generally recommended?

☐ Yes, reason:

The firmware update / hardware exchange can be performed by means of:

• Flashing the new firmware by means of service or configuration program

No, reason:

A FW update is recommended for installation places with very low background radiation.

5 Documentation

Instruction manual

Is a new instruction manual required because of the changes in point 2?

□ Yes ⊠ No

Which manual corresponds to the new Firmware version / Hardware I revision:

| Device | Communication option | Manual | Documentation code |
|--------|----------------------|----------|--------------------|
| FMG50 | HART | BA01966F | 03.21 |

Safety manual

Is a new safety manual required because of the changes in point 2?

□ Yes ⊠ No

Which safety manual corresponds to the new Firmware version / Hardware I revision:

| Device | Manual | Documentation code |
|--------|----------|--------------------|
| FMG50 | FY01007F | 05.21 |

The new manuals can be downloaded from the Internet:

www.endress.com - area "DOWNLOADS"

- enter the device details and type of manual

6 Price

Has the price of the device changed?

 \Box Yes, new list price and update costs (without installation) are attached

🖾 No