Safety Instructions **Proline Promag P 10**

KCs: Zone 1 Zone 21



XA03093D/06/EN/01.22-00

71595438 2022-12-01





Services

Proline Promag P 10

Table of contents

Associated documentation
Manufacturer's certificates
Manufacturer address
Extended order code 5
Safety instructions: General
Safety instructions: Installation
Safety instructions: Zone 219
Temperature tables
Explosion hazards arising from gas and dust
Connection values: Signal circuits

XA03093D Proline Promag P 10

Associated documentation

For an overview of the scope of the associated Technical Documentation, refer to the following:

- Device Viewer (www.endress.com/deviceviewer): Enter serial number from nameplate.
- Endress+Hauser Operations app: Enter serial number from nameplate or scan matrix code on nameplate.

This document is an integral part of the following Operating Instructions:

Measuring device	Documentation code				
	HART Modbus				
Promag P 10	BA02069D	BA02072D			

Additional documentation

Contents	Document type	Documentation code
Explosion Protection	Brochure	CP00021Z/11

Please note the documentation associated with the device.

Manufacturer's certificates

KC Declaration of Conformity

Certificate number:

- 22-KA4BO-0552X (KC: Ex db ib [ib] IIB T4...T1 Gb)
- 22-KA4BO-0553X (KC: Ex db ib IIB T4...T1 Gb)
- 22-KA4BO-0554X (KC: Ex tb [ib] IIIC T***°C Db)
- 22-KA4BO-0555X (KC: Ex tb IIIC T***°C Db)
- 22-KA4BO-0556X (KC: Ex db ib lib IIB T4...T1 Gb)
- 22-KA4BO-0557X (KC: Ex db ib IIB T4...T1 Gb)
- 22-KA4BO-0558X (KC: Ex tb [ib] IIIC T***°C Db)
- 22-KA4BO-0559X (KC: Ex tb IIIC T***°C Db)

Affixing the certificate number certifies conformity with Protection device Safety Certification Notification No. 2021-22.

Manufacturer address

Endress+Hauser Flowtec AG 35, rue de l'Europe 68700 Cernay France

Endress+Hauser Flowtec (China) Co. Ltd. Su-Hong-Zhong-Lu No. 465 Suzhou Industrial Park 215021 Suzhou Province Jiangsu China

Extended order code

The extended order code is indicated on the nameplate, which is affixed to the device in such a way that it is clearly visible. Additional information about the nameplate is provided in the associated Operating Instructions.

Structure of the extended order code



Device type

The device and the device design is defined in the "Device type" section (Product root).

Basic specifications

The features that are absolutely essential for the device (mandatory features) are specified in the basic specifications. The number of positions depends on the number of features available. The selected option of a feature can consist of several positions.

Optional specifications

The optional specifications describe additional features for the device (optional features). The number of positions depends on the number of features available. The features have a 2-digit structure to aid identification (e.g. JA). The first digit (ID) stands for the feature group and consists of a number or a letter (e.g. J = Test, Certificate). The second digit constitutes the value that stands for the feature within the group (e.g. A = 3.1 material (wetted parts), inspection certificate).

More detailed information about the device is provided in the following tables. These tables describe the individual positions and IDs in the extended order code which are relevant to hazardous locations.

Device type

Position	Order code for	Option selected	Description
1	Instrument family	5	Electromagnetic flowmeter
2	Sensor	P 1)	Sensor type
3	Transmitter	В	Transmitter type: 4-wire, compact version
4	Generation index	В	Platform generation
5, 6	Nominal diameter	Examples: 02, 04, 40, 50, 1H, 1Z, T0, E4 ^{2) 3)}	Nominal diameter of sensor

- 1)
- For replacement transmitter only: X For the exact specification of the nominal diameter, see nameplate For replacement transmitter only: XX 2)
- 3)

Basic specifications

Position 1, 2 Order Code "Approval; Transmitter + Sensor" Option selected	Position 4, 5 Order Code "Output; Input" Option selected	Type of protection
KC	C, U	Ex db ib [ib] IIB T4T1 Gb Ex tb [ib] IIIC T** °C Db
	B, M	Ex db ib IIB T4T1 Gb Ex tb IIIC T** °C Db

Position	Order code for	Option selected	Description
6	Output, input 1	В	4-20mA HART, Pulse/frequency/switch output
		С	4-20mA HART, Pulse/frequency/switch output Ex i
		M	Modbus RS485, 4-20mA
		U	Modbus RS485, 4-20mA Ex i
7	Display; Operation	A	W/o; via communication
		Н	W/o; SmartBlue app
		J	LCD, 2,40"; SmartBlue app
		K	LCD, 2,40"; Touch Screen, SmartBlue app
8	Housing	A	Compact, alu, coated
		P	Remote, alu, coated
17, 18	Device Model	A1	1

Optional specifications

No options specific to hazardous locations are available.

Safety instructions: General

- Staff must meet the following conditions for mounting, electrical installation, commissioning and maintenance of the device:
 - Be suitably qualified for their role and the tasks they perform
 - Be trained in explosion protection
 - Be familiar with national regulations or guidelines (e.g. KS C IEC 60079-14)
- Install the device according to the manufacturer's instructions and national regulations (KS C IEC 60079-14).
- Do not operate the device outside the specified electrical, thermal and mechanical parameters.
- Only use the device in media to which the wetted materials have sufficient durability.
- Refer to the temperature tables for the relationship between the permitted ambient temperature for the sensor and/or transmitter, depending on the range of application, and the temperature classes.
- Alterations to the device can affect the explosion protection and must be carried out by staff authorized to perform such work by Endress+Hauser.
- When using in hybrid mixtures (gas and dust occurring simultaneously), observe additional measures for explosion protection.
- Observe all the technical data of the device (see nameplate).
- Open the housing cover of the transmitter housing in explosion protection Ex db only if one of the following conditions is met:
 - An explosive atmosphere is not present.
 - A waiting time of 10 minutes is observed after switching off the power supply.

The following warning notice is on the device:
WARNING – AFTER DE-ENERGIZING, DELAY 10 MINUTES
BEFORE OPENING ENCLOSURE IN TYPE OF PROTECTION EX D

- Attached nameplates must be included in potential equalization.
- In devices with damaged Ex d threads:
 - Use in hazardous areas is not permitted.
 - Repair of Ex d threads is not permitted.
- Replaced transmitter or sensors shall not be re-used in any other application.

XA03093D Proline Promag P 10

Safety instructions: Installation

- In potentially explosive atmospheres:
 - Do not disconnect the electrical connection of the power supply circuit when energized.
 - Do not open the connection compartment cover when energized.
- The following applies for transmitter with a connection compartment in Ex db IIB:
 - The device may only be opened after a waiting time of 10 minutes after the power supply has been switched off.
- Continuous service temperature of the connecting cable: -40 to +80 °C; in accordance with the range of service temperature taking into account additional influences of the process conditions ($T_{a.min}$ and $T_{a.max} + 20$ K).
- Seal unused entry glands with approved sealing plugs that correspond to the type of protection. The plastic transport sealing plug does not meet this requirement and must therefore be replaced during installation.
- Only use certified cable entries or sealing plugs. The metal sealing plugs supplied meet this requirement.
- Supplied cable glands M20 × 1.5 are only suitable for fixed installation of cables and connections. In the installation, a strain relief must be provided.
- Only use certified cable entries suitable for the application. Observe selection criteria as per KS C IEC 60079-14.
- The following applies when connecting the transmitter with a connection compartment in Ex db:
 Only use separately certified cables and wire entries (Ex db IIB or
 - Ex db IIC) which are suitable for operating temperatures up to 85 °C and for IP 66/67. If using conduit entries, the associated sealing mechanisms must be mounted directly on the housing.
 - Plastic sealing plugs act as transport protection and have to be replaced by suitable, individually approved installation material. The mounted metal thread extensions and blind plugs are tested and certified as part of the housing for type of protection Ex db IIB. The thread extension or the blind plug labeled as follows for identification purposes:
 - Md: M20 x 1.5
 - d: NPT 1/2"
- When the measuring device is connected, attention must be paid to explosion protection at the transmitter.
- Please note the following if using an RFID TAG:
 - The RFID TAG shall never be exposed to high electromagnetic fields according to KS C IEC 60079-14.
 - Electrostatic charge shall be avoided. The RFID TAG shall never be used next to strong charge-generating processes.

 When connecting through a conduit entry approved for this purpose, mount the associated sealing unit directly at the enclosure.

 Only use certified sealing plugs. The metal sealing plugs supplied meet this requirement.

Intrinsic safety

- The device can be connected to the Endress+Hauser service tool FXA291; pay attention to the Operating Instructions. Connection to the service connector is only permitted if the atmosphere is not a potentially explosive atmosphere.
- Observe the guidelines for interconnecting intrinsically safe circuits (e.g. KS C IEC 60079-14, Proof of Intrinsic Safety).
- For display use only battery from Renata type lithium CR1632, 3V.
- The use of the device without a display module is not permitted.

Potential equalization

- Integrate the device into the potential equalization .
- If the ground connection has been established via the pipe as specified, it is also possible to integrate the sensor into the potential equalization system via the pipe.

Safety instructions: Zone 21

- To ensure dust-tightness, securely seal all housing openings, cable entries and sealing plugs.
- Only open all housing briefly, ensuring that no dust or moisture enters the housing.
- Only use certified cable entries and sealing plugs. The metal cable entries, extensions and sealing plugs supplied meet this requirement.

Temperature tables

Ambient temperature

Minimum ambient temperature

 $T_a = -40 \, ^{\circ}\text{C}$

Maximum ambient temperature

 $T_{\text{a}} = +60\,^{\circ}\text{C}$ depending on the medium temperature and temperature class.

Medium temperature

Minimum medium temperature

 $T_{\rm m}$ = -40 to 0 °C depending on the selected device version (see nameplate!)

XA03093D Proline Promaq P 10

Maximum medium temperature

 T_{m} for depending on the maximum ambient temperature T_{a}

Compact version

Maximum medium temperature with or without thermal insulation according to Endress+Hauser specifications

Without thermal insulation


Extended neck for insulation (Optional specification, ID Cx (Sensor Option) = CG), with or without thermal insulation

Liner	T _a	T _m [°C]					
	[°C]	T6 [85 ℃]	T5 [100 °C]	T4 [135 °C]	T3 [200 °C]	T2 [300 °C]	T1 [450°C]
PTFE (110 °C)	55	-	_	110	110	110	110
	60	-	-	100	100	100	100
PTFE (130 °C)	55	-	_	130	130	130	130
	60	-	-	100	100	100	100
PFA	40	-	-	_	150	150	150
	55	-	-	130	130	130	150
	60	-	-	100	100	100	100

With thermal insulation without Endress+Hauser specifications

The specified reference temperature T_{ref} and the maximum medium temperature $T_{m.\,max}$ for each temperature class must not be exceeded:

→ 🖺 10



A002166

- $\blacksquare 1$ Position of reference point for temperature measurement
- 1 Reference point

Reference temperature T_{ref}

T6	T5	T4	T3	T2	T1
[85 ℃]	[100 ℃]	[135 ℃]	[200 ℃]	[300 ℃]	[450 °C]
=	-	69	69	69	

Explosion hazards arising from gas and dust


Determining the temperature class and surface temperature with the temperature table

- ullet In the case of gas: Determine the temperature class as a function of the maximum ambient temperature T_a and the maximum medium temperature T_m .
- \blacksquare In the case of dust: Determine the maximum surface temperature as a function of the maximum ambient temperature T_a and the maximum medium temperature $T_m.$

Example

- Measured maximum ambient temperature: $T_{ma} = 63 \, ^{\circ}\text{C}$
- Measured maximum medium temperature: $T_{mm} = 108 \, ^{\circ}\text{C}$

XAO3093D Proline Promag P 10



A0031267

- 2 Procedure for determining the temperature class and surface temperature
- 1. In the column for the maximum ambient temperature T_a select the temperature that is immediately greater than or equal to the maximum ambient temperature T_{ma} that is present.
 - $T_a = 60 \, ^{\circ}\text{C}$. The row showing the maximum medium temperature is determined.
- 2. Select the maximum medium temperature T_m of this row, which is immediately greater than or equal to the maximum medium temperature T_{mm} that is present.
 - The column with the temperature class for gas is determined: $108 \,^{\circ}\text{C} \le 130 \,^{\circ}\text{C} \to T4$.
- 3. The maximum temperature of the temperature class determined corresponds to the maximum surface temperature for dust: T4 = 135 °C.

Connection values: Signal circuits

The following tables contain specifications which are dependent on the transmitter type and its input and output assignment. Compare the following specifications with those on the nameplate of the transmitter.

Safety-related values

Order code "C	Output; input"	Terminal assignment	Safety-related values
	Current output 4 to 20 mA HART (active)	26 (+), 27 (-)	
Option B	Current output 4 to 20 mA HART (passive)	24 (+), 25 (-)	
	Pulse/frequency/switch output	22 (+), 23 (-)	$U_{N} = 30 V_{DC}$ $U_{M} = 250 V_{AC}$
	Current output 4 to 20 mA (active)	26 (+), 27 (-)	
Option M	Current output 4 to 20 mA (passive)	24 (+), 25 (-)	
	Modbus RS485	22 (B), 23 (A)	$U_{\rm N} = 3.3 \ V_{\rm DC}$ $U_{\rm M} = 250 \ V_{\rm AC}$

Intrinsically safe values

Order code "C	Order code "Output; input"		Safety-related values
Option C	Current output 4 to 20 mA HART (active)	26 (+), 27 (-)	$\begin{array}{c} U_0 = 22.3 \text{ V} \\ l_0 = 93 \text{ mA} \\ P_0 = 520 \text{ mW} \\ L_0 = 8 \text{ mH} \\ C_0 = 500 \text{ nF} \\ \\ U_i = 6.5 \text{ V} \\ l_i = 10 \text{ mA} \\ P_i = 20 \text{ mW} \end{array}$
	Current output 4 to 20 mA HART (passive)	24 (+), 25 (-)	$\begin{split} U_i &= 30 \text{ V} \\ l_i &= 100 \text{ mA} \\ P_i &= 1.25 \text{ W} \\ L_i &= 0 \mu\text{H} \\ C_i &= 6 \text{ nF} \end{split}$
	Pulse/frequency/switch output	22 (+), 23 (-)	$\begin{split} U_i &= 30 \text{ V} \\ l_i &= 100 \text{ mA} \\ P_i &= 1.25 \text{ W} \\ L_i &= 0 \mu\text{H} \\ C_i &= 10 \text{ nF} \end{split}$

XA03093D Proline Promag P 10

Order code "	Output; input"	Terminal assignment	Safety-related values
Option U	Current output 4 to 20 mA (active)	26 (+), 27 (-)	$\begin{array}{c} U_0 = 22.3 \text{ V} \\ l_0 = 93 \text{ mA} \\ P_0 = 520 \text{ mW} \\ L_0 = 8 \text{ mH} \\ C_0 = 500 \text{ nF} \\ \\ U_i = 6.5 \text{ V} \\ l_i = 10 \text{ mA} \\ P_i = 20 \text{ mW} \end{array}$
	Current output 4 to 20 mA (passive)	24 (+), 25 (-)	$U_{i} = 30 \text{ V}$ $l_{i} = 100 \text{ mA}$ $P_{i} = 1.25 \text{ W}$ $L_{i} = 0 \mu\text{H}$ $C_{i} = 6 \text{ nF}$
	Modbus RS485	22 (B), 23 (A)	$\begin{array}{c} U_i = 4.2 \ V \\ l_i = N/A \\ P_i = N/A \\ L_i = 0 \ \mu H \\ C_i = 6 \ nF \\ \\ U_0 = 4.2 \ V \\ l_0 = 120 \ mA \\ P_0 = 130 \ mW \\ L_0 = 10 \ mH \\ C_0 = 900 \ \mu F \\ L_0/R_0 = 1.2 \ mH/\Omega \end{array}$





www.addresses.endress.com