

# Brief Operating Instructions ISEmax CAM40/CAS40

## Ion-selective electrode system



These instructions are Brief Operating Instructions. For detailed information, please read the Operating Instructions and the special instructions on the supplied CD-ROM.

KA427C/07/en/12.08 71092678



## Table of contents

1	Safety instructions	. 3
1.1 1.2	Designated use	. 3
1.3	Operational safety	. 4
2	Installation	. 4
2.1	Incoming acceptance, transport, storage	. 4
2.2	Installation instructions	. 5
2.3	Installation example	. 6
2.4	Post-installation check	. 7
3	Wiring	7
<b>3</b>	Wiring.	.7
<b>3</b> 3.1 3.2	Wiring. Electrical connection to the transmitter	.7 .7
<b>3</b> 3.1 3.2 3.3	Wiring. Electrical connection to the transmitter Sensor connection Optional cleaning unit connection	.7 .7 .9
<b>3</b> 3.1 3.2 3.3 3.4	Wiring. Electrical connection to the transmitter Sensor connection . Optional cleaning unit connection Post-connection check	.7 .7 .9
<b>3</b> 3.1 3.2 3.3 3.4	Wiring. Electrical connection to the transmitter Sensor connection Optional cleaning unit connection Post-connection check	.7 .7 .9 10
3 3.1 3.2 3.3 3.4 4	Wiring. Electrical connection to the transmitter Sensor connection . Optional cleaning unit connection Post-connection check Commissioning .	.7 .7 .9 10
<b>3</b> 3.1 3.2 3.3 3.4 <b>4</b> 4.1	Wiring.         Electrical connection to the transmitter         Sensor connection         Optional cleaning unit connection         Post-connection check         Commissioning         Function check	.7 .7 .9 10 11

## 1 Safety instructions

#### 1.1 Designated use

The ion-selective electrode system is designed for measuring tasks in the activated sludge basin and the inlet of the activated sludge basinof municipal sewage treatment plants.

The following parameters can be monitored depending on the device version:

- Nitrate
- Ammonium
- Potassium (to compensate ammonium)
- Chloride (to compensate nitrate)
- pH value

Any other use than the one described here compromises the safety of persons and the entire measuring system and is not permitted.

The manufacturer is not liable for damage caused by improper or non-designated use.

## 1.2 Installation, commissioning and operation

- The device/measuring system may only be installed, connected, operated and maintained by trained technical personnel (e.g. certified electrician). The technical personnel must strictly adhere to the Operating Instructions, prevailing standards, legal regulations and certificates (depending on application).
- If the Brief Operating Instructions do not provide sufficient information, you must read the Operating Instructions. There, you can find detailed information on the device.
- The operator may only perform modifications and repairs of the device/measuring system that are explicitly permitted in the Operating Instructions.
- Do not operate damaged products and secure them against unintentional commissioning. Mark the damaged product as being defective.
- If faults can not be rectified, the products must be taken out of service and secured against unintentional commissioning.

## 1.3 Operational safety

The assembly has been designed and tested in accordance with the latest industry standards and left the factory in perfect functioning order.

Relevant regulations and standards have been met.

As the user, you are responsible for complying with the following safety conditions:

- Guidelines for explosion protection
- Installation instructions
- Local prevailing standards and regulations.

```
Gaution!
```

Pay attention to the technical data on the name plate!

# 2 Installation

### 2.1 Incoming acceptance, transport, storage

- Make sure the packaging is undamaged! Inform the supplier about any damage to the packaging. Keep the damaged packaging until the matter has been settled.
- Make sure the contents are undamaged! Inform the supplier about damage to the contents. Keep the damaged products until the matter has been settled.
- Check that the order is complete and agrees with your shipping documents.
- The packaging material used to store or to transport the product must provide shock protection and humidity protection. The original packaging offers the best protection. Also, keep to the approved ambient conditions (see "Technical data").
- If you have any questions, please contact your supplier or your local sales center.

## 2.2 Installation instructions

#### Caution!

- The reference electrode or the optional pH electrode are supplied with a protection cap. If you remove the sensor from the medium for an extended period (> 20 min.), you have to put the protection cap, which is filled with 1–3 M KCl solution, back onto the reference electrode or pH electrode. In this way, you avoid irreparable damage resulting from the unit drying out.
- The ion-selective electrodes do not have a protection cap and should never be fitted with such a cap since removing the cap would damage the membrane.
- The compressed air supply should not exceed 3.5 bar (50 psi) as this could damage the relay.
- The compressed air must be supplied through an air filter (5 μm). This filter is already installed in the optional cleaning unit (-> Accessories).



- Select a measuring place that is easily accessible so that no hazards for operating staff can occur.
- Select a measuring place with representative concentration levels and sufficient flow.
- If mounting the transmitter outdoors, you must use a weather protection cover which you can order as an accessory.

#### Installing at the measuring point

1. Secure the transmitter to an upright post, a railing or a wall.

#### 2. Air bubbles

Air bubbles can form in the electrodes after transporting the sensor or if the sensor is stored in a horizontal position. These air bubbles cause measuring errors.

- a. Before installing the sensor, eliminate any air bubbles by gently shaking the unit for example.
- b. Then make sure to only hold the sensor in an upright, vertical position (electrodes pointing downwards) until the sensor is installed at the measuring point.
- 3. Where necessary, install additional electrodes into the sensor and connect them to the suitable cable connector. -> "Wiring" In addition, adapt the sensor configuration (number of parameters, address of the measuring channel, electrode type, measuring unit). -> "Commissioning/Addressing the sensor" and "Operation/Sensor data/Sensor menu"
- 4. Mount the sensor using the optional bracket. The sensor has to be immersed in the medium up to the thread adapter nut and be at a distance of approx. 0.5 m (1.64 ft) from the basin rim.
- 5. Route the cables in such a way that no mechanical damage or interference influences can arise from other cables.
- 6. Connect the optional cleaning unit to the transmitter and the pressurized hose (OD 8) to the sensor.

## 2.3 Installation example

A complete measuring system comprises:

- CAM40 transmitter
- CAS40 sensor
  - Ion-selective electrode(s) for ammonium and/or nitrate
  - Reference electrode
  - Ion-selective electrode for compensating cross-interference
  - pH glass electrode

Optional

- Upright post with boom
- Wall retainer
- Weather protection cover absolutely essential if mounting the transmitter outdoors!
- Compressed air generator (if no compressed air is available on site)



3

Fig. 1: Example: measuring system on basin rim

- 1 CAM40 transmitter
- 2 Upright post with weather protection 4 cover

CAS40 sensor Compressed air supply (cleaning)

#### 2.4 Post-installation check

- After mounting, check all the connections to ensure they are secure and leak-tight.
- Check all cables and hoses for damage.
- Check whether the cables are routed such that they are free from electromagnetic interference influences.

# 3 Wiring

## 3.1 Electrical connection to the transmitter

	Terminal	Assignment
L         Power supply           N         230 V AC           PE         Relay LV 1           PE         (Limit value 1)           Relay LV 2         1           1         (Limit value 2)           2         Relay LV 3           3         (Limit value 2)           2         Relay LV 3           4         Relay LV 4           5         (Limit value 4)           6         Relay Error           7         (Alarm relay)           9         10           22         (Channel 1.4)           24         26           27         Ground           28         Ground	L1, N 1, 2 3, 4 5, 6 7, 8 9, 10 21, 22 23, 24 25, 26 27, 28 PE, PE	230 V AC power supply Relay 1, max. 230 V AC, 2 A Relay 2, max. 230 V AC, 2 A Relay 3, max. 230 V AC, 2 A Relay 4, max. 230 V AC, 2 A Analog output 1 Analog output 2 Analog output 3 Analog output 4 Protective earth Note! A compressor can optionally be controlled to terminals 9 and 10. In such instances, relay 5 is no longer available.

## 3.2 Sensor connection

Connect the sensor(s) directly to the transmitter via the cable connector.

- You can connect a maximum of 2 sensors to CAM40.
- You can install a maximum of 3 electrodes in every sensor. However, a maximum of only 4
  measuring parameters can be displayed and output at the transmitter.
- Compressed air is supplied to two sensors by means of a common cleaning unit.

Sensor	Version 1	Version 2	Version 3
Sensor 1	<ul><li>Ammonium</li><li>Potassium (compensation)</li></ul>	<ul><li>Ammonium</li><li>Potassium (compensation)</li></ul>	<ul><li>Ammonium (no compensation)</li><li>pH</li></ul>
Sensor 2	<ul><li>Nitrate</li><li>Chloride (compensation)</li></ul>	<ul> <li>Ammonium (no compensation)</li> <li>Nitrate (no compensation)</li> </ul>	<ul><li>Nitrate</li><li>Chloride (compensation)</li></ul>

#### Sensor/parameter combinations when using two sensors (examples!):

#### Electrode connection in the sensor:

Electrode	Color of the screw head	Color of the membrane cap	Cable label
Ammonium	RD	RD	1
Nitrate	BU	GY	2
Potassium	YE	ВК	3
Chloride	ВК	ВК	3
Reference	-	-	GN/YE
рН	-	-	2 or 3 (depending on version)

#### Caution!

Free cable ends always have to be provided with a protection cap (—> "Spare parts"). Otherwise, moisture may cause short-circuits.

## 3.3 Optional cleaning unit connection

1. Connect the cleaning unit to the CAM40 transmitter by applying the voltage L1 to terminals 9 and 10 (relay 5).



Fig. 3:

- 2. Go to the "General data" menu (—> "Operation/Operating structure").
- 3. Scroll to the third page with www. If the cursor is disabled, enable it by pressing → + www simultaneously.
- 4. Scroll to the "Menue" item with  $\mathbf{N}$ .
- 5. Select the "ValveMnu" function ( $\bigcirc -> \bigcirc -> \bigcirc$ ).
- 6. Under the "Water" function in the ValveMnu menu, configure the value  ${\bf 04096}.$
- 7. Exit the ValveMnu by selecting "MainMnu" under "Menue" ( $\square \rightarrow \square \rightarrow \square$ ).
- 8. From the main menu, you can go back to the "General data" display with May.

## 3.4 Post-connection check

Checks	Notes
Is the supply voltage correct?	100 to 240 V DC
Are the installed cables strain-relieved and not twisted?	
Are all the cable entries installed, firmly tightened and leak-tight?	

# 4 Commissioning

## 4.1 Operating concept

Call up a menu				MENU	J																	
Call up	the e	editir	ıg mo	de					₽	+ M	enu											
Naviga	te in	the n	nenu							,												
Scroll									MENL	J												
Select function/position				₽																		
Chang	e posi	tion/	'value	9						,	<b>/</b>											
Save th	ne set	tings							Cur	sor o	n "M	enu",	₽	twic	e							
You have to wait 10 minutes before the If you want to save your changes immer "Sensor data" main menu. Otherwise, the changes are lost if you so				e the nmea rou sv	settii liatel vitch	ngs an y, you off th	re sav 1 hav ne de	ed au e to s vice l	itoma elect pefore	ticall "Save 10 r	y to t e data ninut	he EE " und es ha	EPRO ler "D ve ela	M. Visplay Apsed	y∕cha	inge"	in th	e				
Exit th	e mei	าน							MENL	J												
Chara	cters	avai	lable	for	user-	defir	ied fi	elds	:													
	А	В	С	D	E	F	G	Η	Ι	J	K	L	М	Ν	0	Р	Q	R	S	Т	U	V
	W	Х	Y	Ζ	а	b	с	d	e	f	g	h	i	j	k	1	m	n	0	р	q	r
~	s	t	u	v	w	х	у	Z		!	"	#	\$	%	&	,	(	)	*	+	,	-
		/	0	1	2	3	4	5	6	7	8	9	:	;	<	=	>	?	@			

## 4.2 Operating matrix



Endress+Hauser

## 4.3 Switching on the measuring system

#### 4.3.1 Switching on the unit

- 1. Remove the protection cap from the reference electrode or pH electrode. Keep the protection cap in a safe place for later use.
- 2. Switch on the main switch of the transmitter (underneath the operating field, left).

## 🛞 Note!

CAM40 performs a self-test for approximately 20 seconds. In doing so, it recognizes all the electrodes connected. In addition, CAM40 starts the automatic cleaning function. The display is inactive during the self-test. The first channel is automatically displayed after the self-test.

During initial commissioning with factory settings, the display changes to the next measuring channel every 6 seconds.

#### 4.3.2 Selecting a language

- 1. Use 🛃 to navigate to the "General data" display and call up the main menu (🔤).
- 3. Under "Menue", select the "Parameter" submenu (🖬 , 🛃 , 🖃 ).
- 4. In the same way, select your preferred software language under the "Language" function.
- 5. Go back to the "General data" main menu using "Menue".
- Save the language setting by selecting the "Save data" option under the "Modifications" function (▲, 굍, ▲, 굍).
- 7. Switch the CAM40 off and then on again. Only now is the language changed.

Software languages available:

- German
- English

Note!

#### 4.3.3 Addressing the sensor



You do not have to change the settings here if you are only connecting one sensor with two electrodes. CAM40 detects the sensor values automatically. In this case, just check the settings.

1. Navigate with 🗗 to the display for the first measuring channel (e.g. ammonium) and call up the main menu (🕬):



- 2. Call up the editing mode (flashing cursor, launch with  $\boxed{2} + \boxed{2}$ ).
- 3. Under "Name Addr" enter a name for this measuring channel (2, ). You can enter a maximum of 12 characters, e.g. "CAS40 NH4".
- 5. Scroll to the second page with was and enter the number of electrodes in the sensor, e.g. "2", under "No of parameter":



- 6. Under "Base address", enter the address for the measuring channel, e.g. "01" for the electrode of the first sensor that is connected to cable 1. You can also specify a second title. This is displayed in the measuring channel under the name of the measuring channel ("Name Addr", see Point 3).
- 7. Go back to the measuring display.



- Your settings are accepted automatically after 10 minutes. Alternatively, you can choose "Save data" in the main menu under "Modification" and switch CAM40 off and then on again.
- Under "Name Addr" enter an individual name such that users can easily distinguish between the measuring channel displays. This is particularly important if you are connecting two sensors with the same electrode types.

#### 4.3.4 Working with two sensors (optional)

### Note!

The settings are accepted automatically after 10 minutes.

Alternatively, you can choose "Save data" in the main menu under "Modification" and switch CAM40 off and then on again. The settings are then accepted immediately.

#### Addressing the second sensor

- 1. Switch the CAM40 off.
- 2. Disconnect the cable connector of the first sensor from the transmitter.
- 3. Connect the second sensor to the second plug-in jack that has not yet been used.
- 4. Switch on the CAM40 and wait for the self-test to be completed (approx. 20 seconds).
- 5. In the main menu of the first measuring channel (e.g. nitrate), assign a new name ("Name Addr") for this measuring channel.
- 6. Go to the sensor menu and configure the number of parameters and the base address of the first electrode (e.g. "03" if the first sensor is already using "01" and "02"). Also assign a second title.
- 7. For every additional measuring channel of the second sensor, also assign the base address and a second title. For this purpose, go to the main menu of the measuring channel and repeat steps 5 and 6 (base address e.g. "04").

#### Measuring with two sensors

- 1. Switch the CAM40 off.
- 2. In addition to the second sensor, also reconnect the first sensor to the transmitter.
- 3. Switch the CAM40 on and wait for the self-test to be completed.
- 4. Navigate through all the measuring channels (max. 4). You should see the individual name and the address of every channel on the display.
- 5. Make the necessary settings for every measuring channel in the main menu in question (-> "Operation").

#### Displaying the hypertrends of all the measuring channels

1. Switch to the display for "General settings":



2. Go to this menu and scroll to the 3rd page ("Hypertrend/Datalogger"):

* * * * Hypertrend	d / Datalogger * * * *
Statuscurve	:> No
No of windows	:> 01
Output values	: > Normal
Resolution	: > 00.10 min
Time range	: > 024.0 h
Menue	: > MainMnu

- 3. Configure the value "02" for the "No of windows".
- 4. Go back to the measured value display.
- 5. Go to the display for "Hypertrends" (second screen):



6. In the "Hypertrends" menu, assign the address of the measuring channel for the first and, if applicable, for the second curve and specify the title which should be displayed for the curve:

********       Hypertrend       ********         Range       :> 024.0 h         Scaling       :> 008.0 h         **********       1.       Curve         Adress       :> 03         Title       :> Ammonium         Start point       :> 00.00 mg/l         End point       :> 20.00 mg/l         ***********       Curve         Adress       :> 04         Title       :> Potassium		
Range       :> 024.0 h         Scaling       :> 008.0 h         **********       1. Curve *********         Adress       :> 03         Title       :> Ammonium         Start point       :> 00.00 mg/l         End point       :> 20.00 mg/l         ************************************	******* Hv	pertrend *******
Scaling         :> 008.0 h           **********         1. Curve *********           Adress         :> 03           Title         :> Ammonium           Start point         :> 00.00 mg/l           End point         :> 20.00 mg/l           *********         Curve ********           Adress         :> 04           Title         :> Potassium	Range	: > 024.0 h
***********1. Curve ********* Adress :> 03 Title :> Ammonium Start point :> 00.00 mg/l End point :> 20.00 mg/l ************************************	Scaling	: > 008.0 h
Adress         :>         03           Title         :>         Ammonium           Start point         :>         00.00 mg/l           End point         :>         20.00 mg/l           *********         Curve ********           Adress         :>         04           Title         :>         Potassium	**********1.	Curve * * * * * * * * * *
Title         :> Ammonium           Start point         :> 00.00 mg/l           End point         :> 20.00 mg/l           **********         2. Curve *********           Adress         :> 04           Title         :> Potassium	Adress	: > 03
Start point         :>         00.00 mg/l           End point         :>         20.00 mg/l           **********         2.         Curve ********           Adress         :>         04           Title         :>         Potassium	Title	: > Ammonium
End point :> 20.00 mg/l *********2. Curve ********* Adress :> 04 Title :> Potassium	Start point	: > 00.00 mg/l
**********2. Curve ********* Adress :> 04 Title :> Potassium	End point	: > 20.00 mg/l
Adress :> 04 Title :> Potassium	**********2.	Curve * * * * * * * * * *
Title : > Potassium	Adress	: > 04
	Title	: > Potassium
Start point :> 00.00 mg/l	Start point	: > 00.00 mg/l
End point : > 50.00 mg/l	End point	: > 50.00 mg/l

7. Switch back to the measured value display.

#### Your measuring point is now working with two sensors.

## 4.4 Calibration

A calibration is necessary:

- During initial commissioning
- Each time an electrode or membrane cap is replaced
- In the event of implausible measured values



Condition the sensor for at least 1 hour in the medium before the first calibration and each time the membrane cap and electrode are replaced.

#### 4.4.1 Calibration modes

The following calibration modes are available:

- Offset calibration
  - Standard method for all ion-selective electrodes
- Two-point calibration
  - Standard method for the pH electrode
  - Alternative for ion-selective electrodes (ammonium, nitrate) if the offset calibration does not return the desired result
- Standardaddition
  - Alternative for compensation electrodes (potassium, chloride) if offset calibration is not possible since a laboratory value cannot be determined, for example

#### 4.4.2 Offset calibration (ion-selective electrodes)

#### Note!

The section below describes the calibration if the activated sludge basin is the point where the sensor is being used. If you use the sensor in the inlet to the sludge activation, you have to use a higher standard concentration for the calibration, e.g. 50 mg/l.

#### Preparing to calibrate

- 1. Take 31 (0.79 US gal.) of sample from the sewage treatment plant outlet.
- 2. Have some of the sample analyzed in the laboratory for the parameter to the calibrated.
- 3. Press 🛃 to switch off rinsing.
- 4. Add 2 ml (0.068 fl.oz.) standard (1 mol/l  $\cong$  14 g/l) to 2 l (0.52 US gal.) of the sample. Concentration of the sample with standard added [mg/l] = laboratory measured value [mg/l] + 14 mg/l.
- 5. Transfer the sample with the standard to a suitable container and immerse the sensor into it.

-> The measured value display increases.

#### Configuring the offset

- 1. Select the measuring channel of the parameter you want to calibrate.
- 2. Press the key.
- 3. Hold 🖪 down and also press 🔤 until the cursor appears.
- 4. Using **[3]**, navigate to the "Calibration/actual value" menu item.
- 5. Enter the concentration of the sample with the standard.
- 6. Make sure that the "Offset" calibration mode is set under "Calibration/method".
- 7. Navigate to the "Menue" menu item, select "MainMnu" and press 🛃.

#### Calibration

- 1. During calibration, move the sensor in the container. This ensures the necessary flow to the ion-selective electrode.
- Press the key.
   An electrode symbol is displayed in addition to other symbols. The transmitter measures and averages the current sensor signal.
- 3. Wait until the electrode symbol disappears. This can take several minutes in some circumstances.
- Press the key again.
   -> The "Actual value" set in the menu is displayed. After an internal delay period, all the symbols disappear and the display changes to the measuring channel.
- 5. Ammonium only:

Make sure that the value for "Slope" in the measuring channel display is > 90%. If this is not the case, the electrode is used up and has to be replaced.

10 The new calibration data are saved automatically after 10 minutes.

#### Checking the calibration

- 1. Immerse the sensor into a suitable container with drinking water.
- Compare the measured value to the specifications for drinking water.
   The measured value has to drop to the local concentration for drinking water (e.g. ammonium in Germany: < 0.5 mg/l.)</li>
- 3. If the measured value does not meet expectations:
  - a. Repeat offset calibration.
  - b. If the repeated calibration is not successful, you have to record another calibration point using a sample with less standard added:
    - Add 0.2 ml (0.0068 fl.oz.) standard (1 mol/l  $\cong$  14 g/l) to 2 l (0.52 US gal.) of a sample from the sewage treatment plant outlet. Concentration of the sample with standard added [mg/l] = laboratory measured value [mg/l] + 1.4 mg/l.
    - In the menu, set the new, low concentration of the sample with the standard as the current value.
    - Rinse the sensor thoroughly with outlet water before transferring it from the sample with more standard added to the sample with less standard added. This prevents sample being carried over from one container to the next.
    - Perform the calibration as described.
    - In the calibration menu, navigate to the "Menue" item and select "CalMnu".
    - Navigate to "Menue" again and select "CalPoints".
    - In the list that follows, the high value and the low value have to be displayed at the top.
    - Under "Execute cal", select the "2-Point" value and go back to the measuring channel.

**1** Calibration with a second, low value is only required on rare occasions.

#### 4.4.3 Two point calibration (pH electrode, ion-selective electrodes)

This example describes two-point calibration for pH measurement. The same process applies for ion-selective electrodes.

#### Preparing to calibrate

- 1. Prepare two Endress+Hauser pH quality buffers in a suitable vessel (min. 1 l) (or two standard solutions for ammonium or nitrate).
- 2. Go to the main menu of the measuring channel to be calibrated.

3. On Page 1, configure "Two-point" as the method:

```
Name Addr: 03 :> CAS40 - pH
****** Sensor data *******
Slope
         :> 094.8 %
Offset
             : > -1.29 px
Electrode
              :> pH
Zeroline
              :> 00.00
* * * * * * * * Calibration * * * * * * * *
Actual value
             : > 07.00
              : > 2-Point
Method
******** General ********
Start position : > Measure
Check type
             : > Off
              : > Manual
Auto zero
```

- 4. Scroll to Page 3 of the main menu and select "CalMnu" for menu.
- 5. Scroll to Page 2 of this menu and configure the pH values of your buffer solutions under two-point calibration, e.g. 7 and 4 (or the concentrations of the standard solutions for ammonium or nitrate):

```
***** Manual correction ******
Value :> +00.0 ppm
**** Temperature calibration ****
Temperatur :> 025.0 C
******** Calibration *******
1. Buffer :> 07.00
2. Buffer :> 04.00
Measuring mode :> C-Curve
Menue :> CallMnu
```

6. Go back to the measured value display.

#### Calibration

- 1. Press 🚺 to switch off rinsing.
- 2. Immerse the sensor into the first buffer solution, e.g. pH 7 and wait until the measured value has stabilized.
- Press the level.
   Wait until the electrode symbol disappears.
- 4. Immerse the sensor into the second buffer solution, e.g. pH 4 and wait until the measured value has stabilized.
- 5. Press the 🔳 key.

-> Wait until the electrode symbol disappears.

- 6. This concludes the calibration.
- 10 The new calibration data are saved automatically after 10 minutes.

#### 4.4.4 Standardaddition (alternative for compensation electrodes)

Standardaddition is only necessary if offset calibration is not possible for compensation electrodes (potassium or chloride).

#### Preparing to calibrate

- 1. Place the sensor in a suitable vessel with 1 1 (0.26 US gal.) of drinking water.
- 2. Press 🔝 to switch off rinsing.
- 3. Go to the main menu of the measuring channel (e.g. potassium) and configure "StdAdd" for the method on Page 1:



4. Scroll to Page 3 of the main menu and select "CalMnu" for menu.

5. Under Standardaddition on Page 1, enter the probe volume, the standard concentration, the standard volume and the number of steps (= number of calibration points):



🚹 "Flowrate" here means the volume of standard added per step.

6. Go back to the measured value display.

#### Calibration

1. Press the 🔳 key.

-> Wait until the electrode symbol disappears. The text "+1.0 ml" with a black background appears on the right of the display (if you entered 1.0 ml for the flowrate).

- 2. Add 1 ml standard solution to the sample. Move the sensor during the measurement to generate the necessary flow.
- 3. Press the 🔳 key.

 $\rightarrow$  Wait until the electrode symbol disappears. The text "+2.0 ml" appears on the display (if you entered "2" or more for the number of steps).

- Add 1 ml standard solution to the sample again. Move the sensor during the measurement to generate the necessary flow.
   Wait until the electrode symbol disappears.
- 5. If you selected more than 2 steps, repeat the process for adding standard and taking measurements until all the calibration points are recorded.
- 6. Press the key to end the calibration.
   → The current value of the potassium or chloride concentration appears on the display.
- **1** The new calibration data are saved automatically after 10 minutes.

#### 4.4.5 Calibrating the temperature

1 Here, enter a reference value that you determined with an external measurement.

- 1. Go to the main menu of the first measuring channel (e.g. ammonium).
- 2. Scroll to Page 3 and select "CalMnu" for menu.

3. Go to Page 2 of the CalMnu and specify the measured reference temperature for "Temperature calibration":

```
***** Manual correction ******
Value :> +00.0 ppm
*** Temperature calibration ***
Temperatur :> 025.0 C
******* Calibration *******
1. Buffer :> 07.00
2. Buffer :> 04.00
Measuring mode :> C-Curve
Menue :> CalMnu
```

- Go back to the measured value display (www).
   -> The electrode symbol and the hourglass appear on the display.
- 5. Once the electrode symbol has disappeared (the hourglass does not disappear), go back to Page 2 of the CalMnu.
- 6. Go to the "Temperature Calibration" menu item again and press 🛃 to confirm the value.
- Go back to the measured value display (1900).
   -> The hourglass disappears and the temperature value entered is accepted.



People for Process Automation

## Declaration of Hazardous Material and De-Contamination

			_				
KA INO	A No.	λ					

Please reference the Return Authorization Number (RA#), obtained from Endress+Hauser, on all paperwork and mark the RA# cleanty on the outside of the box. If this procedure is not followed, it may result in the refusal of the package at our facility.

Because of legal regulations and for the safety of our employees and operating equipment, we need the "Declaration of Hazardous Material and De-Contamination", with your signature, before your order can be handled. Please make absolutely sure to attach it to the outside of the packaging.

Type of instrument / sensor

Serial number

#### Used as SIL device in a Safety Instrumented System

Process data

Temperature Conductivity \_\_\_\_[°F] \_\_\_\_\_[°C] \_\_\_\_\_ [μS/cm]

Pressure	 [psi]	 [ Pa ]	
Viscosity	[cp]	[mm <sup>2</sup> /s	1

#### Medium and warnings

			<u>/ð\</u>	<u>/&amp;\</u>		<u>/×</u> \		Ŀ
	Medium / concentration	Identification CAS No.	flammable	toxic	corrosive	harmful/ irritant	other *	harmless
Process medium								
Medium for process cleaning								
Returned part cleaned with								

\* explosive; oxidising; dangerous for the environment; biological risk; radioactive Please tick should one of the above be applicable, include safety data sheet and, if necessary, special handling instructions.

#### Description of failure

#### Company data

Company	Phone number of contact person
Address	Fax / E-Mail
	Your order No

"We hereby certify that this declaration is filled out truthfully and completely to the best of our knowledge.We further certify that the returned parts have been carefully cleaned. To the best of our knowledge they are free of any residues in dangerous quantities."

www.endress.com/worldwide





KA427C/07/en/12.08 Printed in Germany / FM+SGML 6.0