Manufacturer Information

for users regarding software updates
(following the NAMUR recommendation 53)

1. Type of device

☒ Field device / signal processing device
☐ Monitoring‑ / operation system / hand held terminal etc.
☐ Modem / interface

Manufacturer	:	Endress+Hauser Flowtec AG
Device	:	Coriolis Flowmeter
Type	:	Promass 100 EtherNet/IP (0x104A)
Order code	:	8A1B-*****N*********

2. Firmware

Previous firmware version	:	1.01.02
New firmware version	:	1.02.01
How can the previous firmware version be identified?	:	• Local display • Nameplate for connections • Configuration and service software e.g. FieldCare
Description of the modifications in comparison to the previous firmware version	:	• Integrated Heartbeat functionality into the Rockwell AOP • New unit "Beer Barrel (BBL)" added

3. Compatibility

Is the operating tool compatible with the installed device firmware?

☐ Yes
☒ No, description:

An update of the DD's (device description) is required for all operating tools in use.

Is a firmware update generally recommended?

☐ Yes:
☒ No, reason:

If the additional properties are not required for the operation of the measurement system, then no firmware update is necessary.

Endress+Hauser

People for Process Automation

Manufacturer Information

for users regarding software updates
(following the NAMUR recommendation 53)

4. Instruction manual

Is a new instruction manual necessary due to the modification of the firmware?

☐ Yes
☒ No

Which manual corresponds to the new firmware?

Device	Communication options	Manual	Identification
Promass 100	EtherNet/IP	Operating instructions	BA01182D/06/EN/01.13

The new instruction manuals can be referred in Internet:
http://www.endress.com   – area „DOWNLOAD"
                                – declaration of the device and kind of manual

5. Price

Change in price of device in comparison with the predecessor version?

☐ Yes, new list price and update costs (without installation) are enclosed
☒ No

Endress+Hauser

People for Process Automation