



Special Documentation

Mounting instructions for the universal adapter

Cerabar, Deltabar, Deltapilot

Universal adapter information


NOTICE

Incorrect preparation for mounting.

The measurement does not function properly and the measuring device may be damaged.

- ▶ Remove the transport protection safely.
- ▶ Do not touch the measuring cell membrane.
- ▶ Ensure that the process seal is seated correctly.

Preparing the universal adapter for mounting



Check that the seal is seated correctly. If necessary, position the seal properly.

