

















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

| 1 | Type | of | device |
|---|------|----|--------|
|---|------|----|--------|

☐ Field device / signal processing device

☐ Monitoring-/operation system/hand held terminal etc.

☐ Modem / interface

Manufacturer : Endress+Hauser GmbH+Co.KG

Device : Micropilot M

: FMR23x/24x (HART and PROFIBUS PA) Type

FMR250 (HART)

Previous software version : FMR23x/24x (HART and PROFIBUS PA) -> V01.02.04

FMR250 (HART) -> V01.01.00

How can the previous software version number be identified:

(a) by standard HART commando #0

(b) by ToF Tool

(c) by Fieldcare / DTM (d) by local operation

Firmware/Software

New firm-/software version : V01.04.00

Description of the modification in comparison with the predecessor version:

(1) Creation of window around the actual echo

(2) Improved evaluation of small echos in the near distance

(3) Improved suppression of increasing noise levels

(4) Improved evaluation of small echos with fluctuating amplitude

(5) Improved tank bottom recognition

(6) Improved filtering of output value

(7) Improved function by merging of echo groups

(8) Optimization of application parameters

(9) Extension of displayed values by one digit

3 Compatibility

Is the newly installed firmware/software compatible with the operating tools?

ToF Tool Field Tool Package version 3.04

HART Communicator DXR375

Rev.: 1, DD Rev.: 1

Fieldcare version 2.02.00 / DTM Library Release A1-2006

☐ No, description:





















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

| Is a | firm/ | 'software | update | generally | recommended? |
|------|-------|-----------|--------|-----------|--------------|
| | | | | | |

☐ Yes, reasons:

The firm-/software update can be performed by means of \dots

⋈ No, reasons:

New software optimizes transmitters behaviour. From a signal processing point of view an upgrade is not necessary.

4 Instruction manual

Is a new instruction manual necessary due to the modification of the firm-/software?

□ No

Which manual corresponds to the new firm-/software:

| Communication opt | ions Manual | Marking | |
|-------------------|---|--|---|
| HART | BA218F/00/de/12.05 | 52006316 | |
| | BA218F/00/en/12.05 | 52006317 | |
| PROFIBUS PA | BA225F/00/de/12.05 | 52008591 | |
| | BA225F/00/en/12.05 | 52008592 | |
| HART | BA219F/00/de/12.05 | 52006318 | |
| | BA219F/00/en/12.05 | 52006319 | |
| PROFIBUS PA | BA226F/00/de/12.05 | 52008593 | |
| | BA226F/00/en/12.05 | 52008594 | |
| HART | BA220F/00/de/12.05 | 52006320 | |
| | BA220F/00/en/12.05 | 52006321 | |
| PROFIBUS PA | BA227F/00/de/12.05 | 52008595 | |
| | BA227F/00/en/12.05 | 52008596 | |
| HART | BA248F/00/de/12.05 | 52012489 | |
| | BA248F/00/en/12.05 | 52012490 | |
| PROFIBUS PA | BA249F/00/de/12.05 | 52012491 | |
| | HART PROFIBUS PA HART PROFIBUS PA HART PROFIBUS PA HART PROFIBUS PA | BA218F/00/en/12.05 PROFIBUS PA BA225F/00/de/12.05 BA225F/00/en/12.05 HART BA219F/00/de/12.05 BA219F/00/en/12.05 PROFIBUS PA BA226F/00/de/12.05 BA226F/00/de/12.05 BA220F/00/de/12.05 BA220F/00/en/12.05 PROFIBUS PA BA227F/00/de/12.05 BA227F/00/de/12.05 BA227F/00/de/12.05 BA248F/00/de/12.05 BA248F/00/en/12.05 | HART BA218F/00/de/12.05 BA218F/00/en/12.05 BA218F/00/en/12.05 BA208591 BA225F/00/de/12.05 BA225F/00/en/12.05 BA225F/00/en/12.05 BA219F/00/de/12.05 BA219F/00/en/12.05 BA219F/00/en/12.05 BA219F/00/de/12.05 BA226F/00/de/12.05 BA226F/00/en/12.05 BA226F/00/en/12.05 BA220F/00/de/12.05 BA220F/00/de/12.05 BA220F/00/de/12.05 BA227F/00/de/12.05 BA227F/00/en/12.05 BA227F/00/en/12.05 BA2248F/00/de/12.05 BA248F/00/en/12.05 BA248P/00/en/12.05 BA248P/00/en/12.05 |





















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

| | | BA249F/00/en/12.05 | 52012492 |
|--------|----------------|--------------------|----------|
| FMR245 | HART | BA251F/00/de/12.05 | 52012495 |
| | | BA251F/00/en/12.05 | 52012496 |
| | PROFIBUS PA | BA252F/00/de/12.05 | 52012497 |
| | | BA252F/00/en/12.05 | 52012498 |
| FMR250 | HART | BA284F/00/de/01.06 | 52025088 |
| | | BA284F/00/en/01.06 | 52025089 |
| | PROFIBUS PA | BA331F/00/de/01.06 | 71007773 |
| | | BA331F/00/en/01.06 | 71007774 |
| FMR2xx | HART / PA / FF | BA221F/00/de/12.05 | 52006322 |
| | | BA221F/00/en/12.05 | 52006323 |
| FMR250 | HART / PA | BA291F/00/de/01.06 | _ |
| | | BA291F/00/en/01.06 | |

The new instruction manuals can be referred in Internet:

http://www.endress.com - area "DOWNLOAD"

- declaration of the device and kind of manual

5 Price

Change in price of device in comparison with the predecessor version?

☐ Yes, new list price and update costs (without installation) are enclosed

⊠ No

