

















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

1 Type of device

□ Field device / signal processing device

☐ Monitoring-/operation system/hand held terminal etc.

☐ Modem / interface

Manufacturer : Endress+Hauser GmbH+Co.KG

Device : Gammapilot M

: FMG60 Type

Previous software version : V01.01.06 FF

How can the previous software version number be identified:

(a) by local operation FHX40 (Group selection-> system parameters

-> protocol+sw-no. (b) by FieldCare

Firmware/Software

New firm-/software version : V01.03.02 FF

Description of the modification in comparison with the predecessor version:

(1) Error code A165 – generated from pulse rate >160~000~c/s- is automatically confirmed after the pulse rate is within the accepted

range again. Power OFF and ON is not longer necessary. (2) New filter functionality for Gamma Modulator FHG65

implemented

3 Compatibility

Is the newly installed firmware/software compatible with the operating tools?

- ⋈ Yes
 - FHX40 (VU331)
 - FieldCare Package Version 1.04.00, FieldCare from V 2.05.00 + DTM Library V 2.20.00, via IPC interface
- ☐ No, description:





4

















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

Is a firm/softw	vare update generally reco	ommended?	
☐ Yes, reason	ns:		
⊠ No, reason	ns:		
This error 500 mm)	code can occur in mines	e A165, generated from pulse rate s at density measurement and empof several detectors or at unpressur).	ty tube (pipe diameter >
Or necess	sary if Gamma Modulator	FHG65 is used.	
Instruction m	nanual		
Is a new instru	iction manual necessary (due to the modification of the firm-	-/software?
⊠ Yes □ No			
Which manual	l corresponds to the new	firm-/software:	
Device	Communication opti		Marking
FMG60	FF	Instruction manual	BA330F/00/en/03.09
FMG60	HART, PA, FF	Description of Instrument	71091971 BA287F/00/en/06.07
FMG60	, ,	Functions	on FieldCare-CD
		Functional safety manual	SD230F/00/en/05.09 No. 71094369
The new instruction http://www.e	uction manuals can be ref	ferred in Internet: DOWNLOAD"	
1111p.// W W W.C		ation of the device and kind of mar	nual

5 Price

Change in price of device in comparison with the predecessor version?

☐ Yes, new list price and update costs (without installation) are enclosed

No

