

Manufacturer Information

for users regarding software updates
(following the NAMUR recommendation 53)

1 Type of device

- Field device / signal processing device
- Monitoring- / operation system / hand held terminal etc.
- Modem / interface

Manufacturer : Endress+Hauser
Device : Process indicator / transmitter
Type : RIA45, RIA46, RMA42
Previous software version : 1.02.zz

How can the previous software version number be identified:

Display of current firmware version at device start-up,
nameplate, parameter in configuration software, parameter in
local set-up

2 Firmware/Software

New firm-/software : 1.03.zz
version

Description of the modification in comparison with the predecessor version:

New parameter "Failure delay" to delay error messages;
parameter is only visible if Signal range=4-20mA or 1-5V and
Namur NE43=on is set.

3 Compatibility

Is the newly installed firmware/software compatible with the operating tools?

- Yes
- No, description:

The new firmware requires a new DTM (FDT-Tool) for device configuration

Is a firm/software update generally recommended?

- Yes, reasons:

The firm-/software update can be performed by means of ...

Endress+Hauser 

People for Process Automation

Manufacturer Information

for users regarding software updates
(following the NAMUR recommendation 53)

No, reasons:

If the additional parameter is not required for measuring operation, no update is necessary

4 Instruction manual

Is a new instruction manual necessary due to the modification of the firm-/software?

- Yes
 No

Which manual corresponds to the new firm-/software:

Device	Communication options	Manual Marking
RIA45	all	Operating instructions BA00272R/09/EN/03.14
RIA46	all	Operating instructions BA00274R/09/EN/02.13
RMA42	all	Operating instructions BA00287R/09/EN/03.13

The new instruction manuals can be referred in Internet:

<http://www.endress.com> - area „DOWNLOAD“
- declaration of the device and kind of manual

5 Price

Change in price of device in comparison with the predecessor version?

- Yes, new list price and update costs (without installation) are enclosed
 No