t-mass T 150

**EN** Installation Instructions: EA01106D → 🖺 3

**DE** Einbauanleitung: EA01106D → 🖺 11



# Safety chain

t-mass T 150

## Table of contents

1	Overview of spare part sets	4
2	Designated use	. 5
3	Personnel authorized to carry out repairs	5
4	Safety instructions	6
5	Symbols used	7
6	Tools list	. 8
7	Special safety instructions	8
8	Before installing the device, secure the safety chain	8
9	Installing the measuring device	9
10	Hooking the safety chain in place	9

#### 1 Overview of spare part sets

The Installation Instructions apply to the following spare part sets:

Order number	Original spare part set	Contents
71240321	Set, safety chain	1 × chain 1 × fastening lug 1 × chain link 2 × screw connection of eyelet

# Can only be used in connection with process connections with PEEK clamping rings.


- The order number of the spare parts set (on the product label on the package) can differ from the production number (on the label directly on the spare part)!
  - You can find the order number of the relevant spare parts set by entering the production number of the spare part in the spare parts search tool.
  - We recommend that you keep the Installation Instructions and packaging together at all times.

#### 2 Designated use

The spare part sets and Installation Instructions are used to replace a faulty unit with a functioning unit of the same type. Only original parts from Endress+Hauser may be used. Only spare parts kits designed by Endress+Hauser for the measuring device can be used at any


Inspection is performed using the W@M Device Viewer. The procedure involved is described as follows.

A spare parts overview is located in the interior of some measuring devices. If the spare parts kit is specified on this list, no inspection is required.



#### 3 Personnel authorized to carry out repairs

Authorization to carry out repairs depends on the measuring device's approval type. The table below shows the authorized group of people in each case.



Whoever carries out the repairs has full responsibility to ensure that work is carried out safely and to the required quality standard. He/she must also quarantee the safety of the device following repair.

Measuring device approval	Personnel authorized to perform repairs <sup>1)</sup>
Without approval	2, 3
With approval (e.g. IECEx)	2, 3
For custody transfer	4

- 1) 1 = Qualified specialist on customer side, 2 = Service technician authorized by Endress+Hauser,
  - 3 = Endress+Hauser (return measuring device to manufacturer)
  - 4 = Check with local approval center if installation/modification must be performed under supervision.

## 4 Safety instructions

- Check whether the spare part matches the labeling on the measuring device as described on the cover page.
- The spare part sets and Installation Instructions are used to replace a faulty unit with a functioning unit of the same type.
   Only use original parts from Endress+Hauser.
- Comply with national regulations governing mounting, electrical installation, commissioning, maintenance and repair procedures.
- The following requirements must be met with regard to specialized technical staff for the mounting, electrical installation, commissioning, maintenance and repair of the measuring devices:
  - Specialized technical staff must be trained in instrument safety.
  - They must be familiar with the individual operating conditions of the devices.
  - In the case of Ex-certified measuring devices, they must also be trained in explosion protection.
- The measuring device is energized! Risk of fatal injury from electric shock. Open the measuring device only when the device is de-energized.
- When using Ex-certified measuring devices: Open device only when in a de-energized state (allow 10 minutes to elapse after switching off the power supply) or in environments which do not have a potentially explosive atmosphere.
- In the case of measuring devices in safety-related applications in accordance with IEC 61508 or IEC 61511: Commission in accordance with Operating Instructions after repair. Document the repair procedure.
- Before removing the device: set the process to a safe state and purge the pipe of dangerous process substances.
- Hot surfaces! Risk of injury! Before commencing work: allow the system and measuring device to cool down to a touchable temperature.
- In the case of devices in custody transfer, the custody transfer status no longer applies once the seal has been removed.
- The Operating Instructions for the device must be followed.
- Risk of damaging the electronic components! Ensure you have a working environment protected from electrostatic discharge.
- After removing the electronics compartment cover: risk of electrical shock due to missing touch protection!
  - Turn the measuring device off before removing internal covers.
- Modifications to the measuring device are not permitted.
- Only open the housing for a brief period. Avoid the penetration of foreign bodies, moisture
  or contaminants.
- Replace defective seals only with original seals from Endress+Hauser.
- If threads are damaged or defective, the measuring device must be repaired.
- Threads (e.g. of the electronics compartment cover and connection compartment cover) must be lubricated if an abrasion-proof dry lubricant is not available. Use acid-free, non-hardening lubricant.

- If spacing is reduced or the dielectric strength of the measuring device cannot be guaranteed during repair work, perform a test on completion of the work (e.g. high-voltage test in accordance with the manufacturer's instructions).
- Service plug:
  - Do not connect in explosive atmospheres.
  - Only connect to Endress+Hauser service devices.
- Observe the instructions for transporting and returning the device outlined in the Operating Instructions.
- If you have any questions, please contact your Endress+Hauser service organization.

# 5 Symbols used

## 5.1 Safety symbols

Symbol	Meaning
<b>▲</b> DANGER	DANGER! This symbol alerts you to a dangerous situation. Failure to avoid this situation will result in serious or fatal injury.
<b>▲</b> WARNING	WARNING! This symbol alerts you to a dangerous situation. Failure to avoid this situation can result in serious or fatal injury.
<b>A</b> CAUTION	CAUTION! This symbol alerts you to a dangerous situation. Failure to avoid this situation can result in minor or medium injury.
NOTICE	NOTE! This symbol contains information on procedures and other facts which do not result in personal injury.

# 5.2 Symbols for certain types of information

Symbol	Meaning
<b>✓</b>	Permitted Procedures, processes or actions that are permitted.
X	Forbidden Procedures, processes or actions that are forbidden.
i	Tip Indicates additional information.
1., 2., 3	Series of steps

#### 6 Tools list



# 7 Special safety instructions


#### **A** CAUTION

#### Risk of injury!


If the coupling is opened incorrectly under process pressure, the sensor will shoot out.

- ▶ Therefore always ensure that no process pressure is applied.
- Before introducing or removing the t-mass T 150: make sure that no process pressure is applied.
- Check screw connections for leaks.
- If threads on parts of the mounting set are damaged or defective, the parts must be repaired
  or the defective parts must be replaced if necessary.
- Hot surfaces! Risk of injury! Before commencing work: allow the system and measuring device to cool down to a touchable temperature.


# 8 Before installing the device, secure the safety chain



 Release the coupling nut (1) and remove the sensor from the socket (2).



 Slide the fastening ring of the safety chain over the socket (1) and insert the sensor into the socket (2).



► Tighten the coupling nut by hand.


# 9 Installing the measuring device

## **A** CAUTION

#### Risk of injury!

Danger due to improper process sealing!

- ▶ Ensure that the seals are clean and undamaged.
- ▶ Ensure that the correct sealing material has been used (e.g. Teflon tape for NPT ¾").
- ► Secure the seals correctly.



- **■** 1 Engineering unit mm (in)
- x Number of turns to tighten

- Ensure that the direction of the arrow on the sensor matches the flow direction of the medium. Ensure the insertion depth and alignment are correct.
- 2. Tighten coupling nut fingertight.
- 3. Tighten coupling nut with x turns (1).
- 4. Mounting for the first time:

Tighten coupling nut with 1  $\frac{1}{4}$  turns (1).


#### Repeat mounting:

Tighten coupling nut with 1 turn (1).




If strong vibrations can be expected, tighten the coupling nut with 1½ turns (1) when mounting for the first time.

# 10 Hooking the safety chain in place



► Open the screw connection on the eyelet of the safety chain.



Hook the eyelet into the bracket on the transmitter. The chain must be taut!

# Sicherungskette

t-mass T 150

## Inhaltsverzeichnis

1	Übersicht Ersatzteilsets	12
2	Bestimmungsgemäße Verwendung	13
3	Reparaturberechtigte Personen	. 13
4	Sicherheitshinweise	. 14
5	Verwendete Symbole	. 15
5	Werkzeugliste	16
7	Spezielle Sicherheitshinweise	. 16
3	Vor dem Einbau des Gerätes: Sicherungskette befestigen	16
9	Einbau Messgerät	. 17
10	Sicherungskette einhängen	. 17

#### 1 Übersicht Ersatzteilsets

Die Einbauanleitung ist für folgende Ersatzteilsets gültig:

Bestell- nummer	Original Ersatzteilset	Inhalt
71240321	Set Sicherungskette	1 × Kette 1 × Befestigungslasche 1 × Kettenglied 2 × Verschluss

# Nur verwendbar in Verbindung mit Prozessanschlüssen mit Klemmringen in PEEK.


- Die Bestellnummer des Ersatzteilsets (auf dem Produktaufkleber der Verpackung) kann sich von der Produktionsnummer (auf dem Aufkleber direkt auf dem Ersatzteil) unterscheiden!
  - Durch Eingabe der Produktionsnummer des Ersatzteiles im Ersatzteilfindetool kann die Bestellnummer des ensprechenden Ersatzteilsets ermittelt werden.
  - Wir empfehlen Einbauanleitung und Verpackung immer zusammen aufzubewahren.

# 2 Bestimmungsgemäße Verwendung

Ersatzteilset und Einbauanleitung dienen dazu, eine defekte Einheit gegen eine funktionierende Einheit des gleichen Typs zu ersetzen. Es dürfen nur Originalteile von Endress+Hauser verwendet werden. Grundsätzlich dürfen nur Ersatzteilsets verwendet werden, die von Endress+Hauser für das Messgerät vorgesehen sind.

Die Überprüfung ist via W@M Device Viewer durchzuführen, die Vorgehensweise dazu ist nachfolgend beschrieben.

Bei einigen Messgeräten befindet sich im Inneren des Gerätes eine Ersatzteilübersicht. Ist das Ersatzteilset dort aufgelistet, entfällt die Überprüfung.



# 3 Reparaturberechtigte Personen

Die Berechtigung zur Durchführung einer Reparatur ist von der Zulassung des Messgeräts abhängig. Die Tabelle zeigt den jeweils berechtigten Personenkreis.



1)

Die Person, die eine Reparatur vornimmt, übernimmt die Verantwortung für die Sicherheit während der Arbeiten, die Qualität der Ausführung und die Sicherheit des Geräts nach der Reparatur.

Zulassung des Messgeräts	Reparaturberechtigter Personenkreis <sup>1)</sup>
ohne Zulassung	2, 3
mit Zulassung (z.B. IECEx)	2, 3
Bei eichfähigem Verkehr	4

- 1 = Ausgebildete Fachkraft des Kunden, 2 = Von Endress+Hauser autorisierter Servicetechniker,
  - 3 = Endress+Hauser (Messgerät an Hersteller zurücksenden)
  - 4 = Mit der lokalen Zulassungsstelle prüfen, ob ein Ein-/Umbau unter Aufsicht erfolgen muss.

#### 4 Sicherheitshinweise

- Prüfen, ob das vorliegende Ersatzteil zur Kennzeichnung auf dem Messgerät passt, wie auf der Titelseite beschrieben.
- Ersatzteilset und Einbauanleitung dienen dazu, eine defekte Einheit gegen eine funktionierende Einheit des gleichen Typs zu ersetzen.
   Nur Originalteile von Endress+Hauser verwenden.
- Nationale Vorschriften bezüglich der Montage, elektrischen Installation, Inbetriebnahme, Wartung und Reparatur einhalten.
- Folgende Anforderungen an das Fachpersonal für Montage, elektrische Installation, Inbetriebnahme, Wartung und Reparatur der Messgeräte müssen erfüllt sein:
  - In Gerätesicherheit ausgebildet.
  - Mit den jeweiligen Einsatzbedingungen der Geräte vertraut.
  - Bei Ex-zertifizierten Messgeräten: zusätzlich im Explosionsschutz ausgebildet.
- Messgerät unter Spannung! Lebensgefahr durch Stromschlag. Messgerät nur im spannungslosen Zustand öffnen.
- Bei Ex-zertifizierten Messgeräten: Nur in spannungslosem Zustand (nach Berücksichtigung einer Wartezeit von 10 Minuten nach Abschalten der Energiezufuhr) oder in Umgebungen öffnen, die keine explosionsfähige Atmosphäre enthalten.
- Bei Messgeräten in sicherheitstechnischen Applikationen gemäß IEC 61508 bzw.
   IEC 61511: Nach Reparatur Neuinbetriebnahme gemäß Betriebsanleitung durchführen.
   Reparatur dokumentieren.
- Vor einem Geräteausbau: Prozess in sicheren Zustand bringen und Leitung von gefährlichen Prozessstoffen befreien.
- Verbrennungsgefahr durch heiße Oberflächen! Vor Arbeitsbeginn: Anlage und Messgerät auf berührungssichere Temperatur abkühlen.
- Bei Messgeräten im abrechnungspflichtigen Verkehr: Nach Entfernen der Plombe ist der geeichte Zustand aufgehoben.
- Die Betriebsanleitung zum Messgerät ist zu beachten.
- Beschädigungsgefahr elektronischer Bauteile! Eine ESD-geschützte Arbeitsumgebung herstellen.
- Nach Entfernen der Elektronikabdeckung: Stromschlaggefahr durch aufgehobenen Berührungsschutz!
  - Messgerät ausschalten, bevor interne Abdeckungen entfernt werden.
- Änderungen am Messgerät sind nicht zulässig.
- Gehäuse nur kurzzeitig öffnen. Eindringen von Fremdkörpern, Feuchtigkeit oder Verunreinigung vermeiden.
- Defekte Dichtungen nur durch Original-Dichtungen von Endress+Hauser ersetzen.
- Defekte Gewinde erfordern eine Instandsetzung des Messgeräts.
- Gewinde (z.B. von Elektronikraum- und Anschlussraumdeckel) müssen geschmiert sein, sofern keine abriebfeste Trockenschmierung vorhanden ist. Säurefreies, nicht härtendes Fett verwenden.

- Wenn bei den Reparaturarbeiten Abstände reduziert oder die Spannungsfestigkeit des Messgeräts nicht sichergestellt werden kann: Prüfung nach Abschluss der Arbeiten durchführen (z.B. Hochspannungstest gemäß Herstellerangaben).
- Servicestecker:
  - Nicht in explosionsfähiger Atmosphäre anschließen.
  - Nur an Servicegeräte von Endress+Hauser anschließen.
- Die in der Betriebsanleitung aufgeführten Hinweise zum Transport und zur Rücksendung beachten.
- Bei Fragen kontaktieren Sie bitte Ihre zuständige Endress+Hauser Serviceorganisation.

# 5 Verwendete Symbole

#### 5.1 Warnhinweissymbole

Symbol	Bedeutung
<b>▲</b> GEFAHR	<b>GEFAHR!</b> Dieser Hinweis macht auf eine gefährliche Situation aufmerksam, die, wenn sie nicht vermieden wird, zu Tod oder schwerer Körperverletzung führen wird.
<b>▲</b> WARNUNG	<b>WARNUNG!</b> Dieser Hinweis macht auf eine gefährliche Situation aufmerksam, die, wenn sie nicht vermieden wird, zu Tod oder schwerer Körperverletzung führen kann.
<b>▲</b> VORSICHT	VORSICHT!  Dieser Hinweis macht auf eine gefährliche Situation aufmerksam, die, wenn sie nicht vermieden wird, zu leichter oder mittelschwerer Körperverletzung führen kann.
HINWEIS	HINWEIS!  Dieser Hinweis enthält Informationen zu Vorgehensweisen und weiterführenden Sachverhalten, die keine Körperverletzung nach sich ziehen.

## 5.2 Symbole für Informationstypen

Symbol	Bedeutung
<b>✓</b>	Erlaubt Abläufe, Prozesse oder Handlungen, die erlaubt sind.
X	Verboten Abläufe, Prozesse oder Handlungen, die verboten sind.
i	Tipp Kennzeichnet zusätzliche Informationen.
1., 2., 3	Handlungsschritte

# 6 Werkzeugliste



# 7 Spezielle Sicherheitshinweise


#### **A** VORSICHT

#### Verletzungsgefahr!


Durch unsachgemäßes Öffnen der Verschraubung unter Prozessdruck wird der Sensor herausschießen.

- ► Es ist deshalb sicherzustellen, dass kein Prozessdruck ansteht.
- Vor Einführung oder Entnahme des t-mass T 150: Sicherstellen dass kein Prozessdruck ansteht.
- Schraubverbindungen auf Leckage prüfen.
- Defekte Gewinde an Teilen des Montagesets erfordern eine Instandsetzung der Teile, oder die defekten Teile müssen, falls notwendig ersetzt werden.
- Verbrennungsgefahr durch heiße Oberflächen! Vor Arbeitsbeginn: Anlage und Messgerät auf berührungssichere Temperatur abkühlen.


# 8 Vor dem Einbau des Gerätes: Sicherungskette befestigen



► Überwurfmutter lösen (1) und Sensor aus Stutzen herausziehen (2).



 Den Befestigungsring der Sicherungskette über den Stutzen schieben (1) und Sensor in Stutzen einführen (2).



► Überwurfmutter von Hand festschrauben.


# 9 Einbau Messgerät

## **A** VORSICHT

#### Verletzungsgefahr!

Gefahr durch mangelnde Prozessdichtheit!

- ▶ Darauf achten, dass die Dichtungen unbeschädigt und sauber sind.
- ▶ Darauf achten, dass korrektes Dichtmaterial benutzt wird (z.B. Teflonband bei NPT ¾").
- ▶ Dichtungen korrekt befestigen.



■ 2 Maßeinheit mm (in)

x Anzahl Umdrehungen für das Anziehen

- Sicherstellen, dass die Pfeilrichtung auf dem Messaufnehmer mit der Durchflussrichtung des Messstoffs übereinstimmt. Korrekte Einstecktiefe und Ausrichtung sicherstellen.
  - 2. Überwurfmutter fingerfest anziehen.
  - 3. Überwurfmutter mit x Umdrehungen anziehen (1).
  - 4. Erstmontage:


Überwurfmutter mit 1 ¼ Umdrehungen (1) anziehen.

#### Wiederholmontage:


Überwurfmutter mit 1 Umdrehung (1) anziehen.

Wenn mit starken Vibrationen zu rechnen ist, dann bei der Erstmontage die Überwurfmutter mit 1½ Umdrehungen (1) anziehen

# 10 Sicherungskette einhängen



 Verschraubung der Öse der Sicherungskette öffnen.



 Öse in Halterung am Messumformer einhaken. Kette muss straff sein!





www.addresses.endress.com