

Manufacturer Information

for users regarding software and hardware updates
(following the NAMUR recommendation 53)

1 Type of device

- ☒ Field device / signal processing device
- ☐ Monitoring- / operation system / hand held terminal etc.

Manufacturer : Endress+Hauser Process Solutions AG

Device : WirelessHART Adapter SWA70

Type : 71089201

Fieldbus / Interface	: Fieldbus WirelessHART / HART	Device Type 0x11F0
----------------------	-----------------------------------	-----------------------

2 Firmware, Hardware I

- ☒ Firmware
- ☐ Hardware I

Old firmware version : 02.40.05

New firmware version : 02.40.06

How can the previous Firmware / Hardware I version number be identified:

Firmware version number can be identified with the plant asset management tool
“FieldCare” and the device driver.

Description of the modification in comparison with the predecessor version:

1. Adapt calculation of HART Device ID and Mac to new Std220 (Serial Number Schematic)

Manufacturer Information

for users regarding software and hardware updates
(following the NAMUR recommendation 53)

3 Compatibility (Firmware, Hardware I)

Is the new Firmware version compatible with the previous version, the installed device drivers, the operating tool compatible / is the new Hardware I version compatible with the previous version?

- ☒ Yes
☐ No, description:

Is a Firmware / Hardware I update generally recommended?

- ☐ Yes, reason:

- ☒ No, reason:
Problems occur during production only.

4 Instruction manual

Is a new instruction manual necessary due to the modification of the software?

- ☐ Yes
☒ No

Which manual corresponds to the new firmware:

Device	Communication options	Manual	Marking
SWA70	HART/WirelessHART	BA00061S/00/EN/22.22-00	WirelessHART Adapter SWA70

The new instruction manuals can be referred in Internet:

<http://www.endress.com> - area „DOWNLOAD“
- declaration of the device and kind of manual

5 Price

Change in price of device in comparison with the predecessor version?

- ☐ Yes, new list price and update costs (without installation) are enclosed
☒ No