## Manufacturer Information

for users regarding software and hardware updates (following the NAMUR recommendation 53)

## Field Xpert SMT50B

New hardware version

| 1 | Type of Product  |   |  |  |  |  |
|---|--|---|--|--|--|--|
|   | <ul><li>Software/hardware for dev</li><li>Modem/interface</li></ul>                  | ice configuration/tablet/handheld/device drivers etc.                             |  |  |  |  |
|   | Manufacturer   | : Endress+Hauser Process Solutions AG   |  |  |  |  |
|   | Product  | : Field Xpert SMT50B  |  |  |  |  |
|   | Type and order code  | : SMT50B  |  |  |  |  |
| 2 | Software, Hardware   |   |  |  |  |  |
|   | Type of change:  |   |  |  |  |  |
|   | <ul><li>☑ Hardware</li><li>☐ Software</li></ul>                                      |   |  |  |  |  |
|   | Previous software version  | : 1.00.xx, 1.01.00, 1.02.00, 1.03.xx, 1.04.00; 1.05.xx; 1.06.00, 1.07.00, 1.08.xx |  |  |  |  |
|   | New software version   | : /   |  |  |  |  |
|   | How can the older software version be identified?                                    | : Inside the software under menu item ? (Help) -> License -> Version              |  |  |  |  |
|   | Description of the modification in comparison with the predecessor software/hardware | : New hardware from a different vendor with significantly improved performance    |  |  |  |  |
| 3 | Compatibility  |   |  |  |  |  |
|   | Is the new software/hardware compatible with the previous version?                   |   |  |  |  |  |
|   |  |   |  |  |  |  |
|   | □ No, reason:  |   |  |  |  |  |



## Manufacturer Information

for users regarding software and hardware updates (following the NAMUR recommendation 53)

|   | Is a software/hardware update generally recommended?  |                        |                               |                      |  |  |
|---|---|------------------------|-------------------------------|----------------------|--|--|
|   | ☑ Yes, reason:  |                        |                               |                      |  |  |
|   | It is recommended to update to the new soft/hardware version of the Field Xpert SMT50B, due to increased performance. |                        |                               |                      |  |  |
|   | □ No, reason:   |                        |                               |                      |  |  |
| 4 | Instruction manual  |                        |                               |                      |  |  |
|   | Is a new instruction manual necessary due to the software modification?   |                        |                               |                      |  |  |
|   | <ul><li>Yes</li><li>No</li></ul>  |                        |                               |                      |  |  |
|   | The manual that cor   | responds to the currer | nt version is:                |                      |  |  |
|   | Product   |                        | Document                      | Document identifier  |  |  |
|   | Field Xpert SMT50   | В                      | Operating Instructions (BA)   | BA02584S/04/EN/01.25 |  |  |
|   |   |                        |                               |                      |  |  |
|   |   |                        |                               |                      |  |  |
|   |   |                        |                               |                      |  |  |
| 5 | Price   |                        |                               |                      |  |  |
| 5 |   | orice in comparison w  | rith the predecessor version? |                      |  |  |

