

















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

1 Type of device

⊠ Field device / signal processing device

☐ Monitoring- / operation system / hand held terminal etc.

☐ Modem / interface

Manufacturer : Endress+Hauser

Device : Memograph for process photometer

Type : CVM40 Previous software : 2.00.06

version

How can the previous software version number be identified:

(a) Display

2 Software

New software version : 2.01.00

Description of the modification in comparison with the predecessor version:

New Features, Enhancements & Improvements

 Additional language packages available for America, Western Europe, Eastern Europe and Asia

- Switching lamp on/off using digital input
- Filter calibration for OUSBT65/66 with filter kit
- Save, protect and restore the factory calibration
- User editable units for OUSTF10
- Display of raw sensor value during calibration
- Robust lamp failure message handling
- Both channels go now to 0mA when turned off





















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

3	Compatibility
	Is the operating tool compatible with the installed device software?
	⊠ Yes
	□ No, description:
	Is a software update generally recommended?
	☐ Yes, reason:
	The software update can be performed by means of
	• USB + PC
	No, reason: ■ No.
	Update only necessary if functional enhancements are desired
	opunce only necessary in runeronal committeements are desired
4	Instruction manual
	Is a new instruction manual necessary due to the modification of the software?
	□ No
	Which manual corresponds to the new software:
	Device Communication options Manual Marking
	CVM40 All BA457CEN_1413.pdf Operating Manual - English
	The new instruction manuals can be referred in Internet: http://www.endress.com - area "DOWNLOAD"
	- declaration of the device and kind of manual
_	
5	Price
	Change in price of device in comparison with the predecessor version?
	☐ Yes, new list price and update costs (without installation) are enclosed☒ No

