



# Manufacturer Information

for users regarding software updates  
(following the NAMUR recommendation 53)

## 1 Type of device

- Field device / signal processing device
- Monitoring- / operation system / hand held terminal etc.
- Modem / interface

Manufacturer : Endress+Hauser Conducta GmbH+Co  
 Device : Liquiline  
 Type : CM42  
 Previous software version : 10.07.01

How can the previous software version number be identified:

- (a) With standard HART or Profibus Communication
- (b) with FieldCare/DTM
- (c) Display

## 2 Firmware/Software

New firm-/software version : 10.07.02

Description of the modification in comparison with the predecessor version:

### Functional improvements

- Alarm LED synchron with Display
- Display of ORP Sensor information and output parameter
- Limit values with decimal places via fieldbus
- Deactivation of temperature sensor with analog sensors
- F218 revoke without restart
- update of lowermost menu item
- Fieldbus download more robust
- faster Profibus response time
- Display of simulation modus via fieldbus

## 3 Compatibility

Is the newly installed firmware/software compatible with the operating tools?

- Yes
- No, description:



## Manufacturer Information

for users regarding software updates  
(following the NAMUR recommendation 53)

Is a firm-/software update generally recommended?

Yes, reasons:

The firm-/software update can be performed by means of ...  
SystemDAT

No, reasons:

Update only necessary if functional enhancements are desired

### 4 Instruction manual

Is a new instruction manual necessary due to the modification of the firm-/software?

Yes

No

Which manual corresponds to the new firm-/software:

Device                      Communication options Manual                      Marking

---

The new instruction manuals can be referred in Internet:

<http://www.endress.com>    - area „DOWNLOAD“  
- declaration of the device and kind of manual

### 5 Price

Change in price of device in comparison with the predecessor version?

Yes, new list price and update costs (without installation) are enclosed

No