

















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

Type of device

☐ Field device / signal processing device

☐ Monitoring-/operation system/hand held terminal etc.

☐ Modem / interface

Manufacturer : Endress+Hauser GmbH+Co.KG

Device : Levelflex M

: FMP40/41C/45 (HART /PA) Type

Previous software version : 01.02.06

How can the previous software version number be identified:

(a) by standard HART commando #0

(b) by ToF Tool

(c) by Fieldcare / DTM

(d) by local operation

Firmware/Software

New firm-/software version : 01.04.00 (from April 2006)

Description of the modification in comparison with the predecessor version:

(1) Creation of window around the actual echo

(2) Automatic adjustment of blocking distances against application

parameter "tank properties"

(3) Gas-Phase Compensation algorithm (4)Improved filtering of output value

(5) Improved function by merging of echo groups

(6) Asymmetric envelope-curve statistic

(7) Prevention of negative level-values

(8) Extension of displayed values by one digit

Compatibility

Is the newly installed firmware/software compatible with the operating tools?

☐ No, description:

- ToF Tool Field Tool Package ab 2.04

- HART Communicator DXR 375

Rev. 1, DD Rev. 1

- Fieldcare Version 02.02.00 / DTM Library Release A1-2006





4

















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

Is a firm/software update generally recommended?
☐ Yes, reasons:
The firm-/software update can be performed by means of
☑ No, reasons:
The new software provides special features for an extended application range. From a signal processing point of view an upgrade is not necessary.
Instruction manual
Is a new instruction manual necessary due to the modification of the firm-/software?

Which manual corresponds to the new firm-/software:

Device	Communication option	ns Manual	Marking
FMP40	HART	BA242F/00/de/01.06	52011929
FMP40	HART	BA242F/00/en/01.06	52011930
FMP40	PROFIBUS PA	BA243F/00/de/01.06	52011931
FMP40	PROFIBUS PA	BA243F/00/en/01.06	52011932
FMP41C	HART	BA276F/00/de/01.06	52021032
FMP41C	HART	BA276F/00/en/01.06	52021033
FMP41C	PROFIBUS PA	BA277F/00/de/01.06	52021034
FMP41C	PROFIBUS PA	BA277F/00/en/01.06	52021035
FMP45	HART	BA279F/00/de/01.06	52021038
FMP45	HART	BA279F/00/en/01.06	52021039
FMP45	PROFIBUS PA	BA280F/00/de/01.06	52021040
FMP45	PROFIBUS PA	BA280F/00/en/01.06	52021041





















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

The new instruction manuals can be referred in Internet: http://www.endress.com - area "DOWNLOAD"

- declaration of the device and kind of manual

5 Price

Change in price of device in comparison with the predecessor version?

 $\hfill \square$ Yes, new list price and update costs (without installation) are enclosured

⊠ No

