

Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

1. Type of device

- ☑ Field device / signal processing device
- □ Monitoring- / operation system / hand held terminal etc.
- □ Modem / interface

Manufacturer	: Endress+Hauser Flowtec AG
Device	: Coriolis Flow Measuring System
Туре	: Promass 80 PROFIBUS PA (0x1528)
Order code	: 80***-*********H

2. Software

Previous firmware version	: 2.03.01
New firmware version	: 3.05.00
How can the previous firmware version be identified?	 Local display Nameplate for connections Configuration and service software e.g. FieldCare
Description of the modifications in comparison to the previous firmware version	New PROFIBUS PA hardwareComm EEPROM error resolved


3. Compatibility

Is the operating tool compatible with the installed device firmware?

- 🗆 Yes
- \boxtimes No, description:

An update of the DD's (device description) is required for all operating tools in use.





Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

Is a firmware update generally recommended?

- □ Yes:
- \boxtimes No, reason:

The new firmware cannot be flash upgraded, because the new PROFIBUS PA hardware is required.

4. Instruction manual

Is a new instruction manual necessary due to the modification of the firmware?

⊠ Yes □ No

Which manual corresponds to the new firmware?


Device	Communication option	s Manual	Identification
Promass 80	PROFIBUS PA	Operating instructions	BA072D/06/en/12.07

The new instruction manuals can be referred in Internet: <u>http://www.endress.com</u> - area "DOWNLOAD" - declaration of the device and kind of manual

5. Price

Change in price of device in comparison with the predecessor version?

 $\hfill\square$ Yes, new list price and update costs (without installation) are enclosed \boxtimes No



People for Process Automation