

Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

1. Type of device

- ☑ Field device / signal processing device
- \square Monitoring- / operation system / hand held terminal etc.
- □ Modem / interface

Manufacturer	: Endress+Hauser Flowtec AG
Device	: Vortex Flow Measuring System
Туре	: Prowirl 72 FOUNDATION Fieldbus (0x1056)
Order code	: 72***_*******K

2. Software

Previous firmware version	: 1.00.00	
New firmware version	: 1.01.00	
How can the previous firmware version be identified?	 Nameplate for connections FOUNDATION Fieldbus configuration/operating software (e.g. NI FBUS Configurator 	
	: • The Fieldbus FOUNDATION Stack was optimized	


3. Compatibility

Is the operating tool compatible with the installed device firmware?

- 🗆 Yes
- \boxtimes No, description:

An update of the DD's (device description) is required for all operating tools in use.





Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

Is a firmware update generally recommended?

- □ Yes:
- \boxtimes No, reason:

The new firmware cannot be flashed, because new Fieldbus FOUNDATION hardware is required.

4 Instruction manual

Is a new instruction manual necessary due to the modification of the firmware?

□ Yes ⊠ No

Which manual corresponds to the new firmware?

Device	Communication options Manual		Identification
Prowirl 72	FOUNDATION Fieldbus	Operating instructions	BA095D/06/en/01.07


The new instruction manuals can be referred in Internet: <u>http://www.endress.com</u> - area "DOWNLOAD"

- declaration of the device and kind of manual

5 Price

Change in price of device in comparison with the predecessor version?

 $\hfill\square$ Yes, new list price and update costs (without installation) are enclosed \boxtimes No



People for Process Automation