

















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

□ Field device / signal processing device

☐ Monitoring-/operation system/hand held terminal etc.

☐ Modem / interface

Manufacturer : Endress+Hauser Flowtec AG
Device : Vortex Flow Measuring System

Type : Prowirl 73 HART (0x57)
Order code : 73***_********A, W

2. Software

Previous firmware version : 1.03.03 New firmware version : 1.04.00

How can the previous

firmware version be

identified?

: • Local display

• Nameplate for connections

Configuration and service software e.g. FieldCare

• Handheld terminal for remote communication e.g. Field Xpert

SFX100

Description of the modifications in comparison to the previous firmware version

 The firmware has been extended with the t-mass 65 Gas-Engine (gas calculator) and with additional natural gas equations. An Energy-Calculator has been implemented that calculates calorific value referred to ISO 6976.

3. Compatibility

Is the operating tool compatible with the installed device firmware?

☐ No, description:

An update of the DD's (device description) is required for all operating tools in use.



















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

	Is a firmware update generally recommended?				
☐ Yes: ☑ No, reason:					
	If the additional properties are not required for the operation of the measurement system, then no firmware update is necessary. 4. Instruction manual Is a new instruction manual necessary due to the modification of the firmware?				
4.					
☐ Yes ☑ No					
	Wł	nich manual co	rresponds to the new fir	mware?	
	De	vice	Communication option	s Manual	Identification
	Pro	owirl 73	HART	Operating instructions	BA094D/06/en/11.08
	The new instruction manuals can be referred in Internet: http://www.endress.com - area "DOWNLOAD" - declaration of the device and kind of manual				
5.	Pri	ce			
	Change in price of device in comparison with the predecessor version? ☐ Yes, new list price and update costs (without installation) are enclosed ☐ No				

