Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

1.	Type of device				
	 □ Field device / signal processing device □ Monitoring- / operation system / hand held terminal etc. □ Modem / interface 				
	Manufacturer	: Endress+Hauser Flowtec AG			
	Device	: Coriolis Flowmeter			
	Туре	: Promass 100 PROFIBUS DP (0x1561)			
	Order code	: 8I1B-**L*****			
2.	Firmware				
	Previous firmware version	. 1.00.02			
	New firmware version	: 1.01.01			
	How can the previous firmware version be identified?	 Local display Nameplate for connections Configuration and service software e.g. FieldCare 			
	Description of the modifications in comparison to the previous firmware version	: • New unit "Beer Barrel (BBL)" added			
3.	Compatibility				
	Is the operating tool compatible with the installed device firmware?				
	☐ Yes☒ No, description:				
	An update of the DD's (device description) is required for all operating tools in us				
	Is a firmware update generally recommended?				

If the additional properties are not required for the operation of the measurement

system, then no firmware update is necessary.

☐ Yes:

 \boxtimes No, reason:

Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

4.	Instruction manual Is a new instruction manual necessary due to the modification of the firmware?					
	□ Yes □ No					
	Which manual corresponds to the new firmware?					
	Device	Communication options Manual Identification		Identification		
	Promass 100	PROFIBUS DP	Operating instructions	BA01251D/06/EN/02. 14		
The new instruction manuals can be referred in Internet: http://www.endress.com - area "DOWNLOAD" - declaration of the device and kind of manual						
5.	Price					
	Change in price of device in comparison with the predecessor version? ☐ Yes, new list price and update costs (without installation) are enclosed ☐ No					