

















Manufacturer Information

for users regarding software- and hardware changes (According to NAMUR-Recommendation 53)

1 Type of device

□ Field device / signal processing device

☐ Monitoring-/ operation system

Manufacturer : Endress+Hauser GmbH+Co.KG, 79689 Maulburg

Device : Deltabar S

Part number/Order code : PMD75, FMD77, FMD78

Fieldbus / Interface : Fieldbus Device Type

V02.20.00, HART Dev Rev 22

2 Firmware, Hardware I

Previous Version : Firmware V02.11.zz, HART, Dev Rev 21 New Version : Firmware V02.20.00, HART, Dev Rev 22

Versionnr:

Previous Version:	New Version:		
2.00.00	2.00.00		

How the current firmware and/or hardware I version number can be detected: Firmware

- 1. by display (Expert -> Communication -> HART-Info -> Software-Revision) or at Start-up
- 2. by FieldCare

Hardware I

- 1. on the I/O Module
- 2. on the spare part sticker on the outside of the housing.





















Manufacturer Information

for users regarding software- and hardware changes (According to NAMUR-Recommendation 53)

Description of the modification in comparison with the predecessor version:

1. Support of HART7

3 Compatibility (Firmware, Hardware I)

Is 1	the new firn	nware ver	sion com	patible	with	the pre	vious	s version	n, the install	led dev	<i>r</i> ice	software
dri	vers, or serv	vice tools	and/or	is the	new	hardwar	e I	version	compatible	with	the	previous
har	rdware I vers	sion?										
	Yes											
\boxtimes	No, descrip	tion:										

1.24.00.

DTM operation is only with new DTM possible. New DTM is included in FieldCare Version

Is a firmware update and/or the exchange of hardware I components generally recommended?

The update/exchange can be performed as follows:

The new DTM/ DD can be downloaded from the internet. The new DTM is included in Fieldcare update $1.24.00\,$

☐ No, reason:

An update is recommended:

 For SIL, Shipbuilding and WHG the certificates are pending. For those devices the old version will be delivered.

Manual

4 Operating Instruction

Is a	new	operating	instruction	necessary	due t	o the	modification	due t	o section 2	?
------	-----	-----------	-------------	-----------	-------	-------	--------------	-------	-------------	---

Yes

□ No

Device

Which operating instruction corresponds to the new firmware and/or hardware I:

Communication options

20.100	o o i i i i i i i i i i i i i i i i i i	171411441	140114110441011
PMD75	HART	Deltabar S	BA00270P/00



Identification



















Manufacturer Information

for users regarding software- and hardware changes (According to NAMUR-Recommendation 53)

FMD77 FMD78 PMD75, FMD77, FMD78

BA00270P/00 BA00270P/00

Pressure Device

The new instruction manuals can be referred in Internet:

http://www.endress.com

- area "DOWNLOAD"

- declaration of the device and kind of manual

5 Price

Does the price of the device change compared to its predecessor version?

 $\hfill \Box$ Yes, new price list and updated costs (without installation) are attached

⊠ No

