Manufacturer Information

For users regarding firmware and hardware updates (in accordance with the NAMUR 53 recommendation)

1 Type of device

| \square | Field device / signal pro Monitoring / operating | . 5 | | | | | |
|--------------------------|-----------------------------------------------------|-----|-------------------------------------|----------------------------------------------------|--|--|--|
| Manufacturer | | : | Endress+Hauser Wetzer GmbH + Co. KG | | | | |
| Product | | : | RIA45, RIA46 | | | | |
| Part number / Order code | | : | | | | | |
| Comi Inter | munication / face | : | Communication 420 mA | Device Type Process indicator with control unit | | | |

2 Firmware, Hardware I

Type of change:

□ Hardware I revision

| Old version / revision | : | 01.03.05 |
|------------------------|---|----------|
| New version / revision | : | 01.03.07 |

How can the old Firmware version / Hardware I revision number be identified:

Indication during start up

Description of the modification with respect to the old Firmware version / Hardware I revision:

Support of additional display driver

3 Functional Safety

Impact on Functional Safety:

⊠ No

🗆 Yes

Changes in safety figures:

- 🖾 No
- \Box Yes \rightarrow new figures refer to Safety Manual (chapter 5)



4 Compatibility (Firmware, Hardware I)

Is the new Firmware version compatible with the previous version, the installed device drivers, the operating tool compatible / is the new Hardware I revision compatible with the previous revision?

🛛 Yes

□ No, description:

Is a Firmware / Hardware I update generally recommended?

☐ Yes, reason:

The firmware update / hardware exchange can be performed by means of:

- Replacement of electronic circuit boards; communication and amplifier module (This procedure is described in the operating instructions of the measuring system).
- Flashing the new firmware by means of; service or configuration program

No, reason:

Only required for new display generation

5 Documentation

Instruction manual

Is a new instruction manual required because of the changes in point 2?

☐ Yes⊠ No

Which manual corresponds to the new Firmware version / Hardware I revision:

| Device | Communication option | Manual | Documentation code |
|--------|----------------------|--------|--------------------|
| | | | |

Safety manual

Is a new safety manual required because of the changes in point 2?

□ Yes

⊠ No

Which safety manual corresponds to the new Firmware version / Hardware I revision:

| Device | Manual | Documentation code | |
|--------|--------|--------------------|--|
|--------|--------|--------------------|--|

 The new manuals can be downloaded from the Internet:

 www.endress.com
 - area "DOWNLOADS"

 - enter the device details and type of manual

6 Price

Has the price of the device changed?

- Yes, new list price and update costs (without installation) are attached
- 🖂 No