



Manufacturer Information

for users regarding software updates
(following the NAMUR recommendation 53)

1 Type of device

- Field device / signal processing device
- Monitoring- / operation system / hand held terminal etc.
- Modem / interface

Manufacturer : Endress+Hauser GmbH+Co.KG, 79689 Maulburg
 Device : Cerabar S
 Type : PMC71, PMP71, PMP75
 Previous software version : V 3.00.08

How can the previous software version number be identified:

Display: During start up and in menu: Transmitterinfo/
 Transmitterdata
 FieldCare: Transmitterinfo/ Transmitterdata

2 Firmware / Software

New firm-/software version : V 4.00.01

Description of the modification in comparison with the predecessor version:
 Diagnostics according to FF 912 (NE 107) is implemented.

3 Compatibility

Is the newly installed firmware/software compatible with the operating tools?

- Yes
- No, description:
 A new Fieldcare DTM is needed.

Is a firm/software update generally recommended?

- Yes, reasons:
 To use the new diagnostics functionality the update is needed.
 The firm-/software update can be performed by means of ...

- No, reasons:



Manufacturer Information

for users regarding software updates
(following the NAMUR recommendation 53)

4 Instruction manual

Is a new instruction manual necessary due to the modification of the firm-/software?

- Yes
 No

Which manual corresponds to the new firm-/software:

Device	Communication option	Manual	Marking
Cerabar S	FOUNDATION Fieldbus	Cerabar S PMC71, PMP71, PMP75 Pressure device	BA

The new instruction manuals can be referred in Internet::

<http://www.endress.com> - Area „DOWNLOAD“
- Name device type and documentation type

5 Price

Change in price of device in comparison with the predecessor version?

- Yes, new list price and update costs (without installation) are enclosed
 No