Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

ı.	Type	ot	de	Vic	e

□ Field device / signal processing device

☐ Monitoring-/operation system/hand held terminal etc.

☐ Modem / interface

Manufacturer : Endress+Hauser Flowtec AG

Device : Vortex Flowmeter

Type : Prowirl 200 HART (0x38)

: 7C2B-*A*****, 7C2B-*B***** Order code

7C2B-*C******, 7C2B-*D*****

2. Software

Previous firmware version : 1.01.01 New firmware version : 1.02.00

How can the previous : • Local display

firmware version be Nameplate for connections

identified? Configuration and service software e.g. FieldCare

Description of the

: • modifications in Additional process variables:

comparison to the previous

firmware version

Pressure

Degree of overheating

No device restart after parameter download

Specific volume

3. Compatibility

Is the operating tool compatible with the installed device firmware?

□ Yes

No, description:

An update of the DD's (device description) is required for all operating tools in use.

Is a firmware update generally recommended?

☐ Yes:

⊠ No, reason:

If the additional properties are not required for the operation of the measurement system, then no firmware update is necessary.



Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

4.	 Instruction manual Is a new instruction manual necessary due to the modification of the firmware? □ Yes □ No 							
	Which manual corresponds to the new firmware?							
	Device Communication options Manual		ns Manual	Identification				
	Prowirl 200	HART	Operating instructions	BA01154D/06/en/03.				
	The new instruction manuals can be referred in Internet: http://www.endress.com - area "DOWNLOAD" - declaration of the device and kind of manual							
5.	Price							
	Change in price of device in comparison with the predecessor version?							
	\square Yes, new list price and update costs (without installation) are enclosed \boxtimes No							