Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

1.	Type of device					
	 □ Field device / signal processing device □ Monitoring- / operation system / hand held terminal etc. □ Modem / interface 					
	Manufacturer	: Endress+Hauser Flowtec AG				
	Device	: Electromagnetic Flowmeter				
	Туре	: Promag 100 EtherNet/IP (0x103A)				
	Order code	: 5P1B-***N******				
2.	Firmware					
	Previous firmware version	: 1.00.03				
	New firmware version	: 1.01.01				
	How can the previous firmware version be identified?	Local displayNameplate for connectionsConfiguration and service software e.g. FieldCare				
	Description of the modifications in comparison to the previous firmware version	 Integrated Heartbeat functionality into the Rockwell AOP New unit "Beer Barrel (BBL)" added 				
3.	Compatibility Is the operating tool compatible with the installed device firmware?					
	☐ Yes ☐ No, description:					
	An update of the DD's (device description) is required for all operating tools in use.					
	Is a firmware update generally recommended?					
	☐ Yes: ☐ No, reason:					

If the additional properties are not required for the operation of the measurement

system, then no firmware update is necessary.



Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

4.	Instruction manual					
	Is a new instruction manual necessary due to the modification of the firmware?					
	☐ Yes ☐ No					
Which manual corresponds to the new firmware?						
	Device	Communication options Manual		Identification		
	Promag 100	EtherNet/IP	Operating instructions	BA01174D/06/EN/02. 14		
	ual					
5.	Price					
	Change in price of device in comparison with the predecessor version?					
	☐ Yes, new list price and update costs (without installation) are enclosed					

⊠ No