## Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

#### 1. Type of device

- ☑ Field device / signal processing device
- $\Box$  Monitoring- / operation system / hand held terminal etc.
- □ Modem / interface

Manufacturer	: Endress+Hauser Flowtec AG	
Device	: Coriolis Flowmeter	
Туре	: Promass 100 PROFIBUS DP (0x1561)	
Order code	: 8P1B-**L******	

#### 2. Firmware

Previous firmware version	: 1.00.02
New firmware version	: 1.01.01
How can the previous firmware version be identified?	<ul> <li>Local display</li> <li>Nameplate for connections</li> <li>Configuration and service software e.g. FieldCare</li> </ul>
Description of the modifications in comparison to the previous firmware version	: • New unit "Beer Barrel (BBL)" added

#### 3. Compatibility

Is the operating tool compatible with the installed device firmware?

- □ Yes
- $\boxtimes$  No, description:

An update of the DD's (device description) is required for all operating tools in use.

Is a firmware update generally recommended?

- □ Yes:
- 🛛 No, reason:

If the additional properties are not required for the operation of the measurement system, then no firmware update is necessary.



# Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

### 4. Instruction manual

Is a new instruction manual necessary due to the modification of the firmware?

□ Yes 🛛 No

Which manual corresponds to the new firmware?

Device	Communication options Manual		Identification
Promass 100	PROFIBUS DP	Operating instructions	BA01253D/06/EN/02. 14

The new instruction manuals can be referred in Internet: http://www.endress.com

- area "DOWNLOAD"

- declaration of the device and kind of manual

## 5. Price

Change in price of device in comparison with the predecessor version?

□ Yes, new list price and update costs (without installation) are enclosed 🛛 No



People for Process Automation