



Manufacturer Information

for users regarding software updates
(following the NAMUR recommendation 53)

1 Type of device

- Field device / signal processing device
- Monitoring- / operation system / hand held terminal etc.
- Modem / interface

Manufacturer : Endress+Hauser GmbH+Co. KG
 Device : Levelflex
 Type : FMP50, FMP51, FMP52, FMP53, FMP54, FMP55, FMP56, FMP57
 Previous software version : 01.00.zz

How can the previous software version number be identified:

1. by display (Expert -> Communication -> HART-Info -> Software-Revision) or at start-up
2. by FieldCare

2 Firmware/Software

New firm-/software version : 01.01.zz
 Description of the modification in comparison with the predecessor version:
 1. Introduction of SIL-menu
 2. Minor Bug fixing

3 Compatibility

Is the newly installed firmware/software compatible with the operating tools?

- Yes
- No, description:

FieldCare: DTM Library Service Version 1.2.5.3213 required

Is a firm/software update generally recommended?

- Yes, reasons:

The firm-/software update can be performed by means of ...

No, reasons:

New software-version due to introduction of SIL-menu (new functionality)

4 Instruction manual

Is a new instruction manual necessary due to the modification of the firm-/software?

Yes

No

Which manual corresponds to the new firm-/software:

Device	Communication options	Manual	Marking
FMP50	HART	BA1000F	Manual
FMP51, FMP52, FMP54	HART	BA1001F	Manual
FMP53	HART	BA1002F	Manual
FMP55	HART	BA1003F	Manual
FMP56, FMP57	HART	BA1004F	Manual
		SD00326	Functional safety manual

The new instruction manuals can be referred in Internet:

<http://www.endress.com>

- area „DOWNLOAD“

- declaration of the device and kind of manual

5 Price

Change in price of device in comparison with the predecessor version?

Yes, new list price and update costs (without installation) are enclosed

No