

















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

1.	Tyne	۸f	device
Ι.	I ype	ΟI	device

□ Field device / signal processing devi	vice
---	------

☐ Monitoring-/operation system/hand held terminal etc.

☐ Modem / interface

Manufacturer : Endress+Hauser Flowtec AG

Device : Ultrasonic Flow Measuring System

Type : Prosonic Flow 92F HART (0x61)

Order code : 92***-******A, W

2. Software

Previous firmware version : 1.00.03 New firmware version : 1.01.01

How can the previous : • Local display

firmware version be • Nameplate for connections

identified? • Configuration and service software e.g. FieldCare

• Handheld terminal for remote communication e.g. Field Xpert

SFX100

Description of the modifications in Addition of new lines sizes DN200/250/300

• Mass flow units (calculated mass flow)

comparison to the previous • Calibration history firmware version

3. Compatibility

Is the operating tool compatible with the installed device firmware?

⊠ Ye:

☐ No, description:

An update of the DD's (device description) is required for all operating tools in use.





















Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

	Is a firmware update generally recommended? ☐ Yes: ☐ No, reason: If the additional properties are not required for the operation of the measurement system, then no firmware update is necessary.							
4.	Instruction manu	ıal						
	Is a new instruction manual necessary due to the modification of the firmware? ☑ Yes ☐ No							
	Which manual corresponds to the new firmware?							
	Device	Communication options Manual		Identification				
	Prosonic Flow 92F	HART	Operating Instructions	BA121D/06/en/13.10				
	The new instruction manuals can be referred in Internet: http://www.endress.com - area "DOWNLOAD" - declaration of the device and kind of manual							
5.	Price							
	Change in price of device in comparison with the predecessor version?							
	\square Yes, new list price and update costs (without installation) are enclosed \square No							

