

## Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

#### 1. Type of device

- ☑ Field device / signal processing device
- □ Monitoring- / operation system / hand held terminal etc.
- □ Modem / interface

Manufacturer	: Endress+Hauser Flowtec AG
Device	: Electromagnetic Flow Measuring System
Туре	: Promag 50 HART (0x41)
Order code	: 50***_***********A, D, S, T, W

## 2. Software

Previous firmware version New firmware version	2.01.02 2.01.03	
How can the previous firmware version be identified?	<ul> <li>Local display</li> <li>Nameplate for connections</li> <li>Configuration and service software e.g. FieldCare</li> <li>Handheld terminal for remote communication e.g. Field Xpert SFX100</li> </ul>	
Description of the modifications in comparison to the previous firmware version	• A Promag 50 upload file created with device firmware 2.01.00 or 2.01.01 cannot be downloaded into a Promag 50 with devi firmware 2.01.02.	


## 3. Compatibility

Is the operating tool compatible with the installed device firmware?

- 🗆 Yes
- $\boxtimes$  No, description:

An update of the DD's (device description) is required for all operating tools in use.





# Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

Is a firmware update generally recommended?

 $\boxtimes$  Yes, reason:

The firmware update fixes problems that otherwise cause the device not to work properly.

□ No:

#### 4. Instruction manual

Is a new instruction manual necessary due to the modification of the firmware?

- □ Yes
- 🛛 No

Which manual corresponds to the new firmware?

Device	Communication options Manual		Identification
Promag 50	HART	Operating Instructions	BA046D/06/en/03.05

The new instruction manuals can be referred in Internet: <u>http://www.endress.com</u> - area "DOWNLOAD"

- declaration of the device and kind of manual

## 5. Price

Change in price of device in comparison with the predecessor version?

 $\hfill\square$  Yes, new list price and update costs (without installation) are enclosed  $\boxtimes$  No



People for Process Automation